

---

**From:** Larry Visoski [REDACTED]  
**Sent:** Wednesday, February 1, 2017 3:50 AM  
**To:** Je vacation  
**Subject:** Fwd: 550 engines

Pete informs it appears Chevron's cleaning service applies the sealant to the Cowl, doesn't seem like a big deal I=will gather more information / facts tomorrow from Kathleen and Gulfstream about this Cowl lip issue

Sent from my iPhone

Begin forwarded message:

From: Pete=Rawson [REDACTED]  
Date: January 31, 2017 at 9:15:57 PM EST  
To: Larry Visoski <[REDACTED]>  
Subject:

<=iv>I saw that too on the due list-  
Code=920004/05 RR NTO 116 Xzilon application cowl inlet lip.  
For some reason this airplane has a Cowl lip issue every 90 days they have to apply this compound do you know what this is? See below

Sent from my iPhone

Begin forwarded message:

From: Larry Visoski: [REDACTED]  
Date: January 31, 2017 at 6:56:14 PM EST  
To: Kathleen Goncalves [REDACTED]  
Subject: 550 engines

Hi Kathleen  
Serial 5173  
Chevron N401H=

Pls keep private,. It's on RRCC  
<=iv id="AppleMailSignature">

We are interested in buying a G550  
But the aircraft we are looking at has this issue can you explain what this is to me in layman's terms? Is there a part shortage?

=font color="#000000">>. 09/03/08 @353.7 hrs GLF-LGB removed corrosion from L/H  
&=mp; R/H Engine Inlet Cowl Lip Skins, performed NDT & re-applied Zzilon3=IAW Rolls-Royce Technical Variance TV  
11807R, Rolls-Royce Service Bulletin B=700-7-710A1-10, and FAA A2-20, C4-11 Gulfstream (GAC) NTO (No Technical  
Obj=ction) No.:116. The NDT report for both Engines revealed that the rem=ining material thickness was above the TV's  
minimum acceptable thickness of=.053"

To terminate any ongoing Technical Variance you must change th= lip skins

Sent from my iPhone

</=iv>

=