
From: ZM <[REDACTED]>
Sent: Tuesday, March 14, 2017 7:33 PM
To: jeffrey E.
Cc: Richard Kahn; ann rodriquez
Subject: Re:

No to water Softener
Yes to new HP Pump
Ye= to reprogramming PLC

Incorrect backwashing procedure and no pre treatment=have fouled membranes and damaged HP Pump Post treatment of water needs to calibrated i.e. Sulphuric acid and Calci=m carbonate injection

Patrick believes the product water is High in ph, bu= low alkalinity and is ionically imbalanced and could be eating away Cister= Walls, hence white residue on fixtures

Once Plant is back online af=er service flush entire system could be 3 to 4 days

Take new water s=mples at RO Product ,cistern and main compound and send state side Lab =

Establish a 1/4 maintenance program

<=r>

Sent from my iPhone

On Mar 14, 2017= at 12:57 PM, jeffrey E. <jeeva=ation@gmail.com <mailto:jeevacation@gmail.com> > wrote:

=atrick advice guides ro

--

= please note

The information contained in this communication i= confidential, may be attorney-client privileged, may constitute insi=e information, and is intended only for the use of the addressee. It is t=e property of

JEE

Unauthorized use, disclosure or copying of this =ommunication or any part thereof is strictly prohibited and may be unlaw=ul. If you have received this communication in error, please notify us i=mediately by return e-mail or by e-mail to jeevacation@gmail.com <mailto:jeevacation@gmail.com> , and

destroy this=communication and all copies thereof,
including all attachments. copyrig=t -all rights reserved

=