

To: Je vacation[ieevacation@gmail.com]
From: [REDACTED]
Sent: Sun 6/13/2010 6:11:41 PM
Subject: Plan

Jeffrey,
Relay chattering becomes less frequent the longer they are powered.
-we are going to swap A & C inverters first and see if problem moves.
-we are going to confirm part number for sense relays, and check availability and have them ready to ship, counter to counter also, as back up. There are three sense relays total and are located next to each other, (for SECOND INV BUS and MAIN INV BUS and INST INV BUS) they look like original equipment from 1974, so may elect to change all three, if they have to be removed to install the INSRT INV BUS sense relay,, I'll install new ones.
I'll keep you posted when inverter swap Is completed and the out come, should be a couple of hour job,
Thank you,
Larry

PS: I have Bill Hammond set to fly with me on June 24th trip.
Sent from my BlackBerry® wireless handheld