

**To:** Je vacation[jeevacation@gmail.com]  
**Cc:** Larry Morrison [REDACTED]  
**From:** [REDACTED]  
**Sent:** Sun 6/13/2010 10:41:25 PM  
**Subject:** Update

Jeffrey,  
I will check the system out in the morning, when it hasn't been powered up for some time.  
Here is Joe's pass down:

Larry,  
Swapped inverters and now it is not failing, I would like to check it a few more times before signing it off though. I also checked the frequency of the A inverter now that they are swapped and it is at 400hz, but the cockpit gauge still shows 406hz, as before the swap. I'm going to leave the inverters swapped so the newer one is in the A inverter position.

I will keep you informed of our findings.

Thanks,  
Joe Higgins  
GDAS PBI weekend avionics lead  
Cell phone [REDACTED]

Sent from my BlackBerry® wireless handheld