
From: Eric Roth [REDACTED]
Sent: Tuesday, April 24, 2018 3:16 PM
To: jeffrey E. [REDACTED]
Cc:
Subject: RE: Open item list and estimated pricing

Working on scheduling to see if we can=accommodate.

As requested and to keep one list cons=lidated, please note the new items 28 (headliner) and 29 (PSU panels) below:

Best Regards,

Eric

ERIC H. ROTH<=> | PRESIDENT

[REDACTED] | www.intljet.=om
<http://www.intljet.com/> <http://twitter.com/#!/intljet> <http://www.facebook.com/intljet>

2221 S=ithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779<=:p>

Jeffrey,

Many of the items below require your d=efinition / confirmation. We have done our best to provide a financia= "feel" for these items. Others are straightforward (airstair steps).

Furthermore, materials need to be selected for the window line, grospoint for closets, etc...

Have a great day!

Eric

<=pan style="font-size:16.0pt;font-family:"HOK Sans Pro Bold",sa=s-serif;color:#A6A6A6">Plan D, LLC

1. = Lav seat in wood \$4,600 - \$=,000
2. = Toilet paper cover – need to discuss design. \$\$1,200 - \$2,400?
3. = Mirror re-do – \$No ch=rg
4. = Aft lav sink drain handle n=eds rubber and tightening \$900 - \$1,400
5. = Coffee maker area – t=ere is no existing fan in this area
6. = Aft galley kettle steam □=11; \$ we do not have a “fix” for removing the steam generated =rom the kettle
7. = Fabricate new lightweight g=alley sink cover - \$ No charge
8. = Divan mod to be determined =nd materials \$96,700* Does not include R/H mid cabin removal of existing d=van? Create new lower sidewall and ledge? Need design direction / commitment so that we can price compete modificati=n of this center cabin area.
9. = New carpet - \$39,800</=:p>
10. Re-veneer fwd side of pocke= door – no peep hole or vacant sign – need definition. C=mplete door?
11. Re-veneer cabin side of aft=lav door cover vacant sign \$800 - \$1,200 if just a cover plate?=/span>
12. Insulate fwd lav door? Need=to discuss potential design \$\$1,800 - \$2,600?
13. Remove windowline monitors =nd recover \$21,360
14. Remove table and lower side=panel “bumpout” at the #3 seat locations \$24,300

15. Fabricate new veneer T.V. c=ver on the L/H forward cabin bulkhead \$3,600
16. iPhone charger at the R/H #= ledge like on GIV \$3,400
17. Raise arms on co-pilot seat=to match pilot seat, make pilot seat softer and stop pilot seat from shaki=g. \$1,600 - \$2,100
18. Fabricate leather arm rest =overs for all cabin single seats \$4,840
19. Stabilize jump seat \$T&= \$400 - \$1,500?
20. New airstair covers \$4,660<=:p>
21. Tighten latches \$ T&M &=8211; estimate \$800 - \$1,400
22. Replace cabin upwash / down=ash lights with new LED lighting \$46,700
23. Replace grospoint on three =3) closets, \$17,600
24. Remove blow out covers at R=H# 3 & L/H #3 seats \$This must stay and are required by Gulfstream
25. Carry on work station \$Need= to be designed to identify pricing. Estimate \$15,000 - \$20,000=/o:p>
26. Organize galley drawers \$ N=ed to know how many drawers, what is in each drawer before pricing
27. Adjust and strengthen side =all table hinges \$T&M
28. Strip and recove= the entry, fwd lav, main cabin, galley and aft lavatory headliner panels =28,960
29. Strip and recove= the PSU panels throughout the aircraft \$26,970

&nbs=;

Best Regards,

Eric

ERIC H. ROTH<=> | PRESIDENT

[REDACTED] | www.intljet.=om
<http://www.intljet.com/> <http://twitter.com/#!/intljet> <http://www.facebook.com/intljet>

2221 S=ithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779<=:p>