
From: Eric Roth <[REDACTED]>
Sent: Saturday, April 21, 2018 1:41 PM
To: jeffrey E.
Cc: [REDACTED]
Subject: Open item list and estimated pricing

Jeffrey,

Many of the items below require your definition / confirmation. We have done our best to provide a financial "feel" for these items. Others are straightforward (airstair steps).

Furthermore, materials need to be selected for the window line, grospoint for closets, etc...

Have a great day!

Eric

Plan D, LLC

1. = Lav seat in wood \$4,600 - \$=,000
2. = Toilet paper cover – need to discuss design. \$\$1,200 - \$2,400?
3. = Mirror re-do – \$No charge
4. = Aft lav sink drain handle needs rubber and tightening \$900 - \$1,400
5. = Coffee maker area – there is no existing fan in this area
6. = Aft galley kettle steam =11; \$ we do not have a "fix" for removing the steam generated from the kettle

7. = Fabricate new lightweight g=ley sink cover - \$ No charge
8. = Divan mod to be determined =nd materials \$96,700* Does not include R/H mid cabin removal of existing d=van? Create new lower sidewall and ledge? Need design direction / commitment so that we can price compete modifiaci=n of this center cabin area.
9. = New carpet - \$39,800<=:p>
10. Re-veneer fwd side of pocke= door – no peep hole or vacant sign – need definition. C=mplete door?
11. Re-veneer cabin side of aft=lav door cover vacant sign \$800 - \$1,200 if just a cover plate?=/span>
12. Insulate fwd lav door? Need=to discuss potential design \$\$1,800 - \$2,600?
13. Remove windowline monitors =nd recover \$21,360
14. Remove table and lower side=panel “bumpout” at the #3 seat locations \$24,300
15. Fabricate new veneer T.V. c=ver on the L/H forward cabin bulkhead \$3,600
16. iPhone charger at the R/H #= ledge like on GIV \$3,400
17. Raise arms on co-pilot seat=to match pilot seat, make pilot seat softer and stop pilot seat from shaki=g. \$1,600 - \$2,100
18. Fabricate leather arm rest =overs for all cabin single seats \$4,840
19. Stabilize jump seat \$T&= \$400 - \$1,500?
20. New airstair covers \$4,660<=:p>
21. Tighten latches \$ T&M &=8211; estimate \$800 - \$1,400
22. Replace cabin upwash / down=ash lights with new LED lighting \$46,700
23. Replace grospoint on three =3) closets, \$17,600
24. Remove blow out covers at R=H# 3 & L/H #3 seats \$This must stay and are required by Gulfstream
25. Carry on work station \$Need= to be designed to identify pricing. Estimate \$15,000 - \$20,000=/o:p>
26. Organize galley drawers \$ N=ed to know how many drawers, what is in each drawer before pricing
27. Adjust and strengthen side =all table hinges \$T&M

Best Regards,

Eric

ERIC H. ROTH<=> | PRESIDENT

P</=pan> 631.737.5900 | C=/b> 516.857.6533 | [REDACTED] | www.intljet.=om
<http://www.intljet.com/> <http://twitter.com/#!/intljet> <http://www.facebook.com/intljet>

2221 S=ithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779<=:p>