

---

**From:** jeffrey E. <jeevacation@gmail.com>  
**Sent:** Saturday, April 21, 2018 1:45 PM  
**To:** Eric Roth  
**Subject:** Re: Open item list and estimated pricing

can you call [REDACTED]. all about right

On Sat, Apr 21, 2018 at 9:41 AM, Eric Roth <[REDACTED]> wrote:<=r>

Jeffrey,

Many of the items below require your definition / confirmation. We have done our best to provide a financial "feel" for these items. Others are straightforward (airstair steps).

Furthermore, materials need to be selected for the window line, grosspoint for closets, etc...=/span>

Have a great day!=/p>

Eric

<=pan style="font-size:16.0pt;font-family:"HOK Sans Pro Bold",sans-serif;color:#a6a6a6">Plan D, LLC

1. Lav seat in wood \$4,600 - \$6,000
2. Toilet paper cover – Need to discuss design. \$1,200 - \$2,400?
3. Mirror re-do – No charge
4. Aft lav sink drain handle need rubber and tightening \$900 - \$1,400
5. Coffee maker area – there is no existing fan in this area

6. Aft galley kettle steam =93 \$ we do not have a "fix" for removing the steam generat=d from the kettle
7. Fabricate new lightweight gall=y sink cover - \$ No charge
8. Divan mod to be determined and=materials \$96,700\* Does not include R/H mid cabin removal of existing diva=? Create new lower sidewall and ledge? Need design direction / commitment so that we can price compete modificati=n of this center cabin area.
9. New carpet - \$39,800=/u>
10. Re-veneer fwd side of pocket d=or – no peep hole or vacant sign – need definition. =omplete door?
11. Re-veneer cabin side of aft la= door cover vacant sign \$800 - \$1,200 if just a cover plate?=/span>
12. Insulate fwd lav door? Need to=discuss potential design \$\$1,800 - \$2,600?
13. Remove windowline monitors and=recover \$21,360
14. Remove table and lower side pa=el "bumpout" at the #3 seat locations \$24,300
15. Fabricate new veneer T.V. cove= on the L/H forward cabin bulkhead \$3,600
16. iPhone charger at the R/H #2 l=dge like on GIV \$3,400
17. Raise arms on co-pilot seat to=match pilot seat, make pilot seat softer and stop pilot seat from shaking.= \$1,600 - \$2,100
18. Fabricate leather arm rest cov=rs for all cabin single seats \$4,840
19. Stabilize jump seat \$T&M \$=00 - \$1,500?
20. New airstair covers \$4,660<=u>
21. Tighten latches \$ T&M =80 estimate \$800 - \$1,400
22. Replace cabin upwash / downwas= lights with new LED lighting \$46,700
23. Replace grospoint on three (3)=closets, \$17,600
24. Remove blow out covers at R/H#=3 & L/H #3 seats \$This must stay and are required by Gulfstream=u>
25. Carry on work station \$Needs t= be designed to identify pricing. Estimate \$15,000 - \$20,000<=>
26. Organize galley drawers \$ Need=to know how many drawers, what is in each drawer before pricing<=u>
27. Adjust and strengthen side wal= table hinges \$T&M

Best Regards,

Eric

ERIC H. ROTH<=> | PRESIDENT

[REDACTED]

-----

[REDACTED]

--

=A0 please note

The information contained i= this communication is confidential, may be attorney-client privileged,=may constitute inside information, and is intended only for the use =f the addressee. It is the property of JEE Unauthorized use, disclos=re or copying of this communication or any part thereof is strictly pro=ibited and may be unlawful. If you have received this communication =n error, please notify us immediately by return e-mail or by e-mail to =a href="mailto:jeevacation@gmail.com" target="\_blank">jeevacation@gmai=.com, and destroy this communication and all copies thereof, inc=uding all attachments. copyright -all rights reserved