

---

**From:** jeffrey E. <jeevacation@gmail.com>  
**Sent:** Thursday, March 24, 2016 1:39 PM  
**To:** Larry Visoski  
**Subject:** Re: GIV update

they repaired the wingleaks recently?

On Thu, Mar 24, 2016 at 9:2= AM, Larry Visoski <

Jeffrey,

Elevator flight con=rol cable was changed due to ware.

While doing flight control ch=cks, Gulfstream mechanic noticed a clicking sound in control yoke, while r=tating aileron yoke.

They removed the Yoke from cock=it, replacing nut plate under floor board in cockpit, time consuming,. Bet=er update on delivery status later today.,Dave and I plan to arrive =t Westfield at noon tomorrow.

Thx

Larry

-----  
Pete and Larry,

Aircraft is still in tail=dock. Wing leak checks ongoing as some panels have leaked and require=corrective action.

O2 bottles installed and leak checked.

We have=run into some challenge's with the yoke repair/installation. This is p=shing our time frame back. We will access any revision to delivery la=er today as work progresses and we can make an accurate estimate.</=iv>

=/div>

Thank You,=C2

Mike Tucker

Gulfstream

Westfield Ma.

Sent from my i=hone

--  
=div class="gmail\_signature">  
=A0 please note

The information contained in this commu=ication is confidential, may be attorney-client privileged, may cons=titute inside information, and is intended only for the use of the addre=see. It is the property of JEE Unauthorized use, disclosure or copyi=g of this communication or any part thereof is strictly prohibited a=d may be unlawful. If you have received this communication in error, pl=ase notify us immediately by return e-mail or by e-mail to

jeevacation@gmail.com, a=d destroy this communication and all copies thereof, including all a=tachments. copyright -all rights reserved