
From: Jermaine Ruan [REDACTED]>
Sent: Friday, February 5, 2016 11:29 PM
To: jeevacation@gmail.com
Cc: [REDACTED]
Subject: Flagpole pool update

Good evening boss

Danny and I deduced that it was the black voltage regulator that trips when the red switch is triggered. We redistributed the load and it appears to have=corrected the problem.

The #2 sub is repaired and working. The old cone leads were dry rotted.

Regards
Jruan

Side note:

The 4 iMacs are on gsj. I will purchase small battery backups for them on Mo=day.

Sent from my iPhone=?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
 <key>conversation-id</key>
 <integer>89678</integer>
 <key>date-last-viewed</key>
 <integer>0</integer>
 <key>date-received</key>
 <integer>1454714973</integer>
 <key>flags</key>
 <integer>8590195713</integer>
 <key>gmail-label-ids</key>
 <array>
 <integer>6</integer>
 <integer>2</integer>
 </array>
 <key>remote-id</key>
 <string>584962</string>
</dict>
</plist>