
From: jeffrey E. <jeevacation@gmail.com>
Sent: Saturday, June 27, 2015 8:59 PM
To: Lvjet
Subject: Re: manifold

if the manifold pressure reading is different from what is=actaullly coming out of the vents what could be the problem?

On Sat, Jun 27, 2015 at 4:56 PM, Lvjet [REDACTED] > wrote:

I spoke to Tech ops,.

45,000 feet, Test flight aircraft report, manifold pressure acceptabl= range is 20psi to 27psi, single pack operation at 41,000 feet is 1= psi to 18psi

we are reading 23psi on left and 26psi on right side manifold pressure= at FL450,. we are good here.

if Sock was freezing,. ice pellets like you heard on B727 would be rol=ing down air ducts according to Gulfstream,. I am have socks changed as pr=ventive Mx.

thx

--

=C2 please note

The information contained in this communic=tion is confidential, may be attorney-client privileged, may constit=te inside information, and is intended only for the use of the addressee=. It is the property of JEE Unauthorized use, disclosure or copying =f this communication or any part thereof is strictly prohibited and =ay be unlawful. If you have received this communication in error, pleas= notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and<=r>destroy this communication and all copies thereof, including all atta=hments. copyright -all rights reserved