
From: jeffrey E. <jeevacation@gmail.com>
Sent: Friday, June 26, 2015 9:03 PM
To: Alireza Ittihadieh
Subject: Re: VP-BBJ Maintenance PO/WO

why is the cockpit aprt?

On Fri, Jun 26, 2015 at 4:04 PM, Alireza =ttihadieh [REDACTED]
<mailto:[REDACTED]> > wrote:<=r>

The reason for the inspections taking longer than 2A quoted is because the =OM is clearing out all due AD's till December.

V-BR
Alireza ITTIHADIEH
From: Alireza Ittihadieh
Sent: Friday, 26 June 2015 20:39
To: =eevacation@gmail.com <mailto:jeevacation@gmail.com>
Cc: Larry Visoski [REDACTED]
Subject: FW: VP-BBJ Maintenance PO/WO

2A Check attached

From: Steve Wi=son [mailto:[REDACTED]]
Sent: Monday, June 15, 2015 9:37 AM
To: Alireza Ittihadieh
Cc: VP-BBJ William Christophe
Subject: VP-BBJ Maintenance PO/WO

Hi Alireza,

Please find PO / Work Scope attached.

Best regards,

Steve Wilson

Mob: + [REDACTED]

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com <<mailto:jeevacation@gmail.com>> , and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved