
From: [REDACTED]
Sent: Tuesday, April 2, 2013 8:52 PM
To: Je vacation
Subject: GIV prebuy update

Jeffrey,
We found cracks in R/H engine fuel nozzle and burner can area.
Cracks also found on L/H engine, Gulfstream still accomplishing borescope.
Once engine borescopes are complete, gulfstream will fwd findings to Rolls Royce for repair plan.
-my next goal is to find cracks in APU.

Sent via BlackBerry by AT&T

```
<?xml version="1.0" encoding="UTF-8"?>
<!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version="1.0">
<dict>
  <key>conversation-id</key>
  <integer>139204</integer>
  <key>date-last-viewed</key>
  <integer>0</integer>
  <key>date-received</key>
  <integer>1364935901</integer>
  <key>flags</key>
  <integer>8623750145</integer>
  <key>gmail-label-ids</key>
  <array>
    <integer>6</integer>
    <integer>2</integer>
  </array>
  <key>remote-id</key>
  <string>287407</string>
</dict>
</plist>
```