
From: Jeffrey Epstein <jeevacation@gmail.com>
Sent: Saturday, September 28, 2013 11:06 PM
To: Larry Visoski
Subject: Re: Some of the Squawks - please read

air gasper - ice drawer. . i suggested using the same c=touts as the g2 for dishes etc. . credenza seperators. headpho=es paper. ? we need to solve my error re table cup holders.=A0

On Sat, Sep 28, 2013 at 6:35 PM, Larry V=soski <████████<mailto:████████> wrote:

GIV will return to Islip Wednesday Oct 3rd evening 7=30pm repairs, The aircraft will be in Islip until Oct 13th. to complete=this list.

#1 item Nose Camera needs be addressed=during this visit.

Divan-

JE notes that t=e foam build up on the GIV is different than the GIIb.

Additionally, J= states that the foam densities on the new back and bottom cushions of the=divan in the GIV are different and noticeable when you deploy the divan to=the berthing position. I want to open up both divans to personally see and=identify the foams that were used. Bottom line is that Jeffrey wants us=to use the foam from the GIIb in the new upholstery for the GIV. (while op=ning the divan, the rear seat divan cushion does not fit into place, requi=es pulling up velcro on seat bottom to adjust so seat back lays flat, the =II is easier to operate, when you extend the divan to bed mode on GII its =ne motion.) seat belts need to be hidden better, the make lump in bed mode= look at GII seat belt storage.

Jeffrey had n=ted previously that he would like the gap between the top of the entry rai= curtain and the headliner kept to an absolute minimum to help keep the no=se out from the entry door to the cabin.

As identified=prior to flight, there are certain lights in the upwash / downwash lightin= that are inoperative and/or intermittent.

Doors =

Aft La=atory to Baggage Door-

L/H #2=Single Seat-

R/H #2=Master Switch Panel-

Galley=and Lavatory Door/Drawers-

Tables=

Entert=ainment System -

Cockpi= Camera- Need nose camera installed or repair of current system. =/u>

- Need Felt or padding on bottom of Microwave chamber= door, to prevent rattles.

-Hinges on doors below=the sink in aft Lav are loose when doors are open,

-When tray tables are open, the mechanism that holds table top firm rests on= fabric side panel, it was discussed to fabricate Titanium or stainless steel (waterfall decorative type of cap to this area would allow the tray table to rest on this surface firming table top, diving board issue still exists.

-Clear rubber/Felt micro pads for tray tables halves, when stowing table the two wood surfaces meet.

- VI= tray table still rattles

-Need Iphone lightening=cord phone charger hard wired for VIP seat, JE mentioned a lightening cord=to come up from bottom of cup holder, since his phone sits in Cup holder during flight.

-See attached photo, JEE request the opening flap =n Tray tables to be Routed longer for easy opening of tray lid.

=img src="cid:377F38D0-C091-4599-9A41-C4C4A73788A4" alt="image.jpeg" height="543" width="728">

<= class="MsoNormal" style="font-family:'Times New Roman',serif">Larry, please add or expand on the items on this list so that we can clearly identify and understand the squawk and so that we all work off of one (1) list to resolve these items.

Sent from my iPad

On Sep 28, 2013, at=12:13 PM, Eric Roth <[REDACTED]<mailto:[REDACTED]>> wrote:

Jay and Larry,

I have exchanged numerous e-mails with Je=frey last night and this morning. Further, Jeffrey and I just spoke on =he phone discussing a few of the squawks.

By no means is below the total list - just a few of th= items that were discussed to be included in a formal list for us to work =ff.

Divan-

JE notes that the foam build up on the GI= is different than the GIIb.

Additionally, JE states that the foam densities on the new back =nd bottom cushions of the divan in the GIV are different and noticeable wh=n you deploy the divan to the berthing position. I want to open up both di=ans to personally see and identify the foams that were used. Bottom lin= is that Jeffrey wants us to use the foam from the GIIb in the new upholst=ry for the GIV.

Entry Curtain-

Jeffrey had noted previously that he woul= like the gap between the top of the entry rain curtain and the headliner =ept to an absolute minimum to help keep the noise out from the entry door =o the cabin.

Main Cabin Area Fluorescent Lighting-<=u>

As identified prior to flight, there are =ertain lights in the upwash / downwash lighting that are inoperative and/o= intermittent.

R/H Galley-

Difficulty deploying the fwd slide out cu=ting board.

<=u>

Doors - </=>

There are a couple of door in the g=iley and aft lavatory that opened in flight.

Aft Lavatory to Baggage Door-

JE identified that the door would not lat=h properly.

<=u>

L/H #2 Single Seat-</=pan>

JE noted that when compa=ed to the R/H #2 seat, the electric seat function controls are not sequenc=d the same (fwd / middle / aft switch functions). Additionally, JE woul= like to know if there is a way to “limit” the recline on this seat so=that the passenger does not “crush” the back of the aft facing double =eat?

R/H #2 Master Switch Panel-=/u>

JE had previously requested that we look =nto if MCC could reprogram the two (2) discarded switch functions to contr=l the shades “ALL UP” and “ALL DOWN”.

Galley and Lavatory Door/Drawers-<=span>

JE had requested we apply the clear bumpers to prevent the doors and drawers from rattling.

Tables-

JE noted difficulty in the deployment / s=owing of the side ledge tables in flight.

Entertainment System -

Obviously we need to send the battery bac=up out for repair/ replacement so that it holds the institute settings of=the head unit.

Cockpit Camera-

Larry, please add or expand on the items on this list =o that we can clearly identify and understand the squawk and so that we al= work off of one (1) list to resolve these items.

Thank you.

ERIC H. ROTH =span style="font-size:9.0pt;font-family:"Arial","sans-serif";color:#644e39"> |
PRESIDENT

<image007.jpg><=>

P 631.737.5900 <tel:631.737.5900> | C 516.857.6533 <tel:516.857.6533> | eroth@intljet.com
<mailto:eroth@intljet.com> | www.intljet.com <http://www.intljet.com/> <image008.jpg>
<http://twitter.com/#!/intljet> <image009.jpg> <http://www.facebook.com/intlje=>

2221 Smithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779=/p>

From: Jeffrey Epstein [mailto:eevacation@gmail.com <mailto:jeevacation@gmail.com>]
Sent: Saturday, September 28, 2013 6:32 AM
To: Eric Roth; vjet
Subject: Re:

Lights out, bed not=right. stereo not working, tables not working. doors not closing or =ot opening. shade switches not working , camera not working. . ap=le tv not working, and more.. I know it will get fixed. and=i appreciate it very much, we are five weeks over. and another week =s needed not hours.

=u>

On Fri, Sep 27, 2013 at 10:07 PM, Eric Roth <[REDACTED] <mailto:[REDACTED]> wrote:

I just sent=Larry an email that we'll speak in the morning- I am very confident th=t we can resolve all items in minimal time(rattling doors, etc....). Obvio=sly want to make sure you are happy.

ERIC H. ROTH | PRESIDENT

P [REDACTED] <tel:[REDACTED]> | C [REDACTED] <tel:[REDACTED]>

[REDACTED] | jeevacation@gmail.com, and
destroy this communication and all copies thereof,
including all attachments. copyright -all rights reserved

</=iv>

--

*****=*****

The information contained in this communication is
confidential, may be attorney-client privileged, may
constitute inside information, and is intended only for
the use of the addressee. It is the property of
Jeffrey Epstein

Unauthorized use, disclosure or copying of this
communication or any part thereof is strictly prohibited
and may be unlawful. If you have received this
communication in error, please notify us immediately by
return e-mail or by e-mail to jeevacation@gmail.com <mailto:jeevacation@gmail.com> , and
destroy this communication and all copies thereof,
including all attachments. copyright -all rights reserved

--

*****=*****

The information contained in this communication is
confidential, may be attorney-client privileged, may
constitute inside information, and is intended only for
the use of the addressee. It is the property of
Jeffrey Epstein

Unauthorized use, disclosure or copying of this
communication or any part thereof is strictly prohibited
and may be unlawful. If you have received this
communication in error, please notify us immediately by
return e-mail or by e-mail to jeevacation@gmail.com <mailto:jeevacation@gmail.com> , and
destroy this communication and all copies thereof,
including all attachments. copyright -all rights reserved

