

---

**From:** Larry Visoski <[REDACTED]>  
**Sent:** Tuesday, November 4, 2014 6:08 PM  
**To:** Je vacation  
**Subject:** Transmission  
**Attachments:** IMG\_1936.JPG; Untitled attachment 00611.txt

The welder noticed the rubber seal as you see in photo would melt if he attempted to weld the cast., taking the unit apart would create more issues since=he's not an FAA repair station., he also felt the weld would become brittle and not supply the support needed., We have two leads on transmission located in California and possible Florida=, they are sending photos shortly., I can install unit as is and shim with washers to grip the current broke pie=e., I hope to have more info once Cali sends photos, or Florida supplier confirm= photos as well, there unit is different manufacture, same part number.,