
From: Larry Visoski [REDACTED]
Sent: Saturday, January 12, 2019 9:35 PM
To: Je vacation
Cc: Larry
Subject: Screenshot G550
Attachments: Image-1.jpg; Untitled attachment 00429.txt; image1.jpeg; Untitled attachment 00432.txt; image1.jpeg; image2.jpeg; Untitled attachment 00435.txt

Jeffrey,

We may have found the issue, the original Wire which was thought to have a break or Open is the Pin 16 Wire. Located behind the:

PDB, "Power Distribution Box" photo below.

Notice Pin 16 which is the trigger for battery contact which is push in on the female connector, You can barely see the Gold pin inside the block, The pins with numbers are used, all the others are spare.,
Gulfstream has to remove the rack and reseat the pin, hoping there is no damage to the connector, that will present other issues with locating parts if we need a new connector.,

Hoping to have better update after the Rack is removed from the plane, around 6pm

Things are improving

Thx
Larry