
From: michael glidden [REDACTED]>
Sent: Monday, February 25, 2019 7:21 PM
To: jeevacation@gmail.com
Cc: [REDACTED]; Richard Kahn; [REDACTED]
Subject: Mold inside master ductwork
Attachments: IMG_0303.JPG; Untitled attachment 01105.txt; IMG_0304.JPG; Untitled attachment 01108.txt; IMG_0305.JPG; Untitled attachment 01111.txt

The light gray section is the normal color.

All the duct in the bath is now being removed also. The bath and the bedroom=are separate systems.