
From: jeffrey E. <jeevacation@gmail.com>
Sent: Saturday, September 2, 2017 7:32 PM
To: Eric Roth; lvjet

90 percent right. most work really great =some ,unfortunatley mostly my fault - bad. some ,(divan=) others just overlooked . fyi it appears t=mp fan in back got disconncted , hot in cabin over the atlantic =A0 , not much fun. but .. it happens\

1

1. the=sides of the cabin door in front are two different colors. ? =C2 very ugly

2 iphone charger not good for flying. not =olid. .

3 I suggest we inset leather on drink rails= cover cup holders and make them smaller. for voss. and find =agnetic charger so phone

4. my captain chair needs a side =ouch low hidden for glasses and pens. we might make the arms w=der on just this chair

5. footrests. need adjustment , =A0 they are currently useless. we should make a small ottoman \ <=div>6. prontos work well and should be installed in place of small s=creens behind the panels on the window line\

7 the table mec=anism needs to be re cut. magnets taken out. and stiffened whe=e it meets the verical panel. which had a lot of rattles =A0 larry has video

8 . I think we should put a stictch on the=tops. they look a little like placemats. without

9 the capt=ins chair needs a repad.

10 the chairs in the cabin were s=aiking quite a bit on take off

11. the psu in the galley which loo=s great shold be changed to white and more down wash lights installed.

12 credenz top should be white to match the galley, and seats like t=e g4

13, we should cover aft bulkhead and lav door with fabric

14 many of the doors and latches were rattling

16. =ver the baggae door we left the old leather , change to white.=br> 17. the psu over the sink should be white and cut back and made s=orter, I kept banging my head when brushing my teeth

18 som= type of cover for toilet paper

19. more cushion on potty seat.=C2 PLENTY of room

20 new potty seat. not nice
=/div>21 rear mag rack, should be covered as well in fabric

22. ba= carrier should have higher sides to lay down books

23 . le=s recover the two front seats in fabric

24. biggest is the DIVAN = almost nothing right. . arms should be higher and eith=r fabric and soft to lean on , they should extend if possible =o the out board wall. the fabric and welting does not look good. =A0 . on the seat cushion , it is deformed, I took =hotos.? the rear cushions are much too hard. angled incorrectl= and the welting was put on the front side instead of the back. =A0 you and i were worried about the corner when you sat back on them. =A0 . when made into a bed, the drink rail is expos=d , and rough we need to rethink the whole .

2=. there is a light on in the bathroom floor that i cant turn off.

26 some of the switchches need to be changed they are old and =attle. same for some latches

27 the new woof covered glassw=re covered rattled like crazy on take off.. putty on the side= of the outboard?\

28 it is going to be great. =A0 . the divan arms look too bulkly and hard maybe cashmere arms wit= foam. not sure

29 odd -but some chair cushions are d=fferent than others. i measured. ? i kept switchin= them around

lots of photos and some videos

--

=C2 please note

The information contained in t=is communication is confidential, may be attorney-client privileged, ma= constitute inside information, and is intended only for the use of =he addressee. It is the property of JEE Unauthorized use, disclosure=or copying of this communication or any part thereof is strictly prohib=ted and may be unlawful. If you have received this communication in =rror, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.c=m, and destroy this communication and all copies thereof, includ=ng all attachments. copyright -all rights reserved

=/div>

--001a11441e2c2a783b055839f0f2-- conversation-id 32898 date-last-viewed 0 date-received 1504380749 flags 8590195713 gmail-label-ids 7 6 remote-id 746158