
From: Larry <[REDACTED]>
Sent: Monday, January 22, 2018 11:15 AM
To: jeffrey E.
Subject: Re:

Yes, I'll certainly look into dirty=connections,,,anything is possible. Appears everything is pointing to #2 AD= area. Air Data Computer.

My first CAS message was:

1-SSEC=message is "Static Source Error Correction" which is define= as Static Source to Error Correction to DADC has been disabled. = 2-No HDG on Co-Pilots DUS while in map mode. Returns if i select=ADC1 to supply data to this unit, normal config is ADC2 runs CoPilots side.=/div> 3-AutoPilot / YAW dampener disengage before decent.
4-N= AutoThrottle before takeoff. Starts to work later in flight.

Gulfstream Mx will arrive this evening, and plan to start on the=plane at 830am tomorrow morn,,, I will discuss this issue with Gulfstream T=ch support in Savanah for their opinion as well in the mean time

Thx
larry

Sent from my iPad

On Jan 22, 2018, at 8:55 AM, jeffre= E. <jeevacation@gmail.com <mailto:jeevacation@gmail.com> &=t; wrote:

Doo= seal leak caused dirt to fly in the electric?

--

please note

confidential, may be a=torney-client privileged, may constitute inside information, and is inte=ded only for the use of the addressee. It is the property of

JEE

U=authorized use, disclosure or copying of this communication or any part t=ereof is strictly prohibited and may be unlawful. If you have received t=is communication in error, please notify us immediately by return e-m=il or by e-mail to jeevacation@gmail.com <mailto:jeevacation@gmail.com> , and destroy this communication and all copi=s thereof, including all attachments. copyright -all rights reserved
=/div>

=