

---

**From:** ZM <[REDACTED]>  
**Sent:** Saturday, February 18, 2017 8:29 PM  
**To:** jeffrey E.  
**Subject:** Re: ZM Update

Jeffrey

There is already a UV and Filters installed underneath the master, I had this in stored during the refurbishment of the master bedroom

This system was designed to polish=treat water from RO Plant or water from the cistern underneath the master.<=div> At this time you maybe better off using the water from the cistern I would need to check water quality before this actually happened As stated the post treatment on the RO plant is not treating the water correctly therefore High PH I will inquire if there is any other form of Post Treatment=available for the Master Bedroom

</=iv>

The same system was installed for cabanas=1 and 2, I noticed this week Instead of=repairing as instructed the UV had totally been disconnected .

Lastly

New pumps have installed for distribution system, I agreed this needed to be done, but there should variable speed drives install to stop hammering the domestic and irrigation system I suspect a lot of the irrigation leaks are caused by the sudden on off of these pumps&nbsp; And more importantly lower water level shut offs should be install to protect pumps if cistern get to low level

I need to get my boots back on the ground again. Will discuss when you visit Zorro

Thank you

</=iv>

Brice

Noting there is also a UV and Filters for cabana 's one and two Noting someone has totally disconnected that treatment

Sent from my iPhone

On Feb 18, 2017, at 12:15 PM, jeffrey E. <jeevacation@gmail.com <mailto:jeevacation@gmail.com>> wrote:

What about water treatment system for lsj , master at least/ !!

On Sat, Feb 18, 2017 at 6:43 PM, Brice Gordon  
Jeffrey

as requested general overview of Zo=ro projects, etc  
jeevacation@gmail.com, a=d  
destroy this communication and all copies thereof,  
including all at=achments. copyright -all rights reserved

=