
From: jeffrey E. <jeevacation@gmail.com>
Sent: Monday, December 19, 2016 9:23 PM
To: Larry Visoski
Subject: Re: GIV gear corrosion inspection issue

friday 6 ok

On Mon, Dec 19, 2016 at 3:51 PM, Larry Visoski [REDACTED] >> wrote:

Jeffrey

Gulfstream found corrosion in Wheel well area, located in area where water collects from wheel spin up,,

not safety of flight or Structural, but needs repair,,

Option 1

TRY to Obtain an extension of 30 to 60 days to repair at later date, stay on schedule for Wed noon completion.

Option 2

Repair by installing a new spliced doubler in the area. (Only maybe the Completion Date would be Friday 6pm) or later after Xmas.?

Option 3

Install new piece, longer down time,, at least Wed mid next week,,

I'm trying to confirm completion dates with all three options above should have more information midmorning tomorrow after Gulfstream engineering reviews, measurements and cleanup of the area are required before Gulfstream gives their opinion for extension or repair.

Sent from my iPhone

--
=div class="gmail_signature" data-smartmail="gmail_signature">
please note

The=information contained in this communication is confidential, may be att=rney-client privileged, may constitute inside information, and is inten=ed only for the use of the addressee. It is the property of JEE U=authorized use, disclosure or copying of this communication or any part=thereof is strictly prohibited and may be unlawful. If you have receive= this communication in error, please notify us immediately by return=e-mail or by e-mail to jeevacation@gmail.com <mailto:jeevacation@gmail.com> , and destroy this communication and al= copies thereof, including all attachments. copyright -all rights reser=ed