
From: Lvjet <[REDACTED]>
Sent: Wednesday, June 10, 2015 5:07 AM
To: jeevacation@gmail.com
Subject: Fwd: R/H engine dog bone
Attachments: IMG_0196.JPG; IMG_0194.JPG; IMG_0193.JPG; IMG_0192.JPG; IMG_0191.JPG

interesting? its the Right Engine Dog Bone that is contacting,. see photos and email below,.

Larry,

Pylon inspections complete and down to close up with no chaffing defects notes.

Checked dog bone on engines as you and James Kreuger discussed and found the R/H engine dog bone making contact with the crane beam. This may be bypassing your crane beam isolator causing your humm. I will send you some photos.

ADC is in work by avionics.

Regards,

Randy LaPlace
Shift Supervisor
[REDACTED]

-----Original Message-----

From: Randy.LaPlace <[REDACTED]>
To: Lvjet [REDACTED]
Sent: Wed, Jun 10, 2015 12:00 am
Subject: R/H engine dog bone

Larry,

These are the photos of the dog bone.

Regards,

Randy LaPlace
Shift
Supervisor

