From: ▮▮▮▮▮▮▮ < ▮▮▮▮▮▮▮ >

Sent: Tuesday, June 26, 2012 8:10 PM

To: Andrew Lasso

Hey Andrew. Rich Kahn from our office suggested changing out the AC units in=both 10B and 10F. If that was the cause of the leak into the wood flooring,=we don't want the same thing to happen again considering we just re did the=wood floors. Apparently one of the AC units in 10F is a 220volt (like the o=e I bought for my apt, but can't use due to the plug not being the same.) w= can move the one from my apt to 10F, then put a normal AC in my apt. Can w= set this up for sometime this week. I'm back in town tonight and will be i= NY for a bit and would love to have a working AC in my apt. Thanks

```
<?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN"
"http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
        <key>date-sent</key>
        <real>1340741406</real>
        <key>flags</key>
        <integer>8590195713</integer>
        <key>original-mailbox</key>
        <string>imap:▮▮▮▮▮▮▮/Sent%20Messages</string>
        <key>remote-id</key>
        <string>11744</string>
        <key>subject</key>
        <string></string>
</dict>
</plist>
```