From: Larry Visoski < ███████████ >
Sent: Wednesday, July 11, 2018 10:41 PM
To: Je vacation
Subject: G550 engine

Jeffrey
While updating the Data bases on G550, Pete noticed a "L Engine Maintenance" code on the panel, He downloaded the information from the aircraft and sent to Rolls Royce for e=aluation, We have this code before During flight, but it clears before landing., Rolls Royce recommends changing the EEC "electronic engine control"
Small computer located on top of the engine,, Part has arrived this evening and will be installed by Gulfstream at JeT avi=tion Teterboro, should be ready to run Engines by 1 PM tomorrow, I will be o= location as well

This part is covered under Rolls Royce Corporate care

Is this ok?

Thx
Larry

Sent from my iPhone=<?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN"
"http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
        <key>conversation-id</key>
        <integer>311948</integer>
        <key>date-last-viewed</key>
        <integer>0</integer>
        <key>date-received</key>
        <integer>1531348853</integer>
        <key>flags</key>
        <integer>8590195717</integer>
        <key>gmail-label-ids</key>
        <array>
                <integer>2</integer>
        </array>
        <key>remote-id</key>
        <string>835951</string>
</dict>
</plist>