From: Richard Kahn █████████████████████

Sent: Monday, May 22, 2017 5:46 PM

To: Eric Roth

Subject: Re: seat prices

thank you for the detailed reply
attached =elow are the figures you sent me on 4-25-2017 which i believe shows =16,800 / 8 seats = 14,600

please advise
thank you

Richard =ahn
HBRK Associates Inc.
575 Lexington =venue 4th Floor
New York, NY 10022

███████████████

From: "jeffrey E." <jeevacation@gmail.com <mailto:jeevacation@gmail.com> >

Subject: Re: G550 sn 5173

Date: April 25, 2017 at 12:30:19 PM EDT

To: Eric Roth ████████████████████████████ >, lvjet ████████████ , Richard =ahn
████████████████████████████

please copy larry =nd rich on all emails

On Tue, Apr 25, 2017 at 12:13 PM, =ric Roth ████████████ wrote:

Date: =.24.17

Client: JE

Aircraft: G550

1

Serial Number: 5173

soft goods

200 Cockpit Area

Price

201 Cockpit Headliner

$ =,767.00

202 Window Line

$ =,294.00

203 Upper Side Wall Panels

$ =,256.00

204 Lower Side Wall Panels

$ =,713.00

205 Glareshield

$ =nbsp;   2,133.50

206 Bulkhead Panels

$ =,058.00

207 Center pedestal

$ =,074.00

208 Crew Seats

$ 11,230.00

209 Control column boots

$ =,459.50

210 Jepp =torage

$ =nbsp; 824.00

211 Crew =rivacy curtain

$ =,022.00

2

225 =loor Covering (Cockpit)

$ =,419.00

230 =ockpit Paint / Touch up

$ =,473.00

300   Entrance Area

Price

301 =eadliner Panels

$ =,620.00

304 Airstair Treatment

$ =nbsp; 4,580.00

311 Fwd =avatory Upper Sidewall Panel

$ =,098.00

314 R/H Fwd Lav Potty Seat

$ =,533.00

320 Jumpseat

$ =,425.00

325 =loor Covering (Entryway)

$ =,272.00

400   Main =abin Area

Price

401 =eadliner Panels

$ =,825.00

402 R/H =amp; L/H PSU / Valance Panels

$ 13,535.00

406 =indow Line Panels

$ =3,915.00

409 Lower Side Panels

$ 14,730.00

412 Fwd =abin Bulkheads

$ =,973.00

416 Aft =abin Bulkheads

$ =,973.00

420 Cabin Single Seats (8)

$ 116,800.00

422 Divan(s) -2-

$ 49,190.00

423 Divan End Arm Cabinets

$ =,392.00

425 Floor Covering

$ 38,235.00

500 Galley Area

Price

501 =eadliner Panels

$ =,897.00

525 =loor Covering (Galley)

$ =nbsp; 636.00

600 Aft Lavatory Area

Price

601 =eadliner Panels

$ =,897.00

606 Potty Seat & Shroud

$ =,794.00

4

611 Aft =avatory R/H Closet

$ =,580.00

612 Aft =avatory L/H Closet

$ =,580.00

625 =loor Covering (Aft Lavatory)

$ =nbsp; 848.00

700 Aft Baggage =rea

Price

701 Recover Panels

$ 11,605.00

703 Baggage Door Vinyl Flap

$ =nbsp; 737.00

725 =loor Covering

$ =,772.00

730 Paint / Touch Up

$ =,505.00

800   Miscellaneous

Price

801 Remove Interior / Inc. Inspection

$ =4,500.00

802 Install Interior / Detail in Aircraft

$ =3,050.00

803 Fire =locking (jump, 3 materials in main)

$ 50,820.00

804 Vertical / Composite Burn Cert.

$ =,566.00

807   Maintenance Runner(s)

$ =,134.00

829 =ngineering / Certificate

$ =,700.00

836 =xterior Paint - ballast for paint

$ =nbsp;   5,020.00

$ 485,460.00

woodwork & finish

800   =iscellaneous

Price

801   Remove Interior / Inc. Inspection

$ =1,850.00

802   Install Interior / Detail in Aircraft

$ =3,653.00

806   Woodwork (all plus finish)

$ 373,267.00

808   Install Placards

$ =,860.00

Hangar Rent

$ 25,000.00

$ 460,630.00

modifications

Mods

Price

317 =orward Crew Galley

$ =,267.00

402 R/H =amp; L/H PSU / Valance Panels - closeout

$ =,425.00

406 =indow Line Panels

$ =,789.00

407 R/H =amp; L/H Drinkrail / Ledges

$ =,572.00

410 Side =all Tables (rare earth mag, supports)

$ 19,865.00

417 Aft =abin Curtain (acoustic, track, magnets)

$ =,050.00

424 =redenza

$ =4,975.00

427 Aft =/H Closet (new cabin)

$ 22,340.00

502 Aft =/H Galley

$ =5,410.00

503 Aft =/H Galley

$ =1,090.00

602 L/H =SU / Valance Panel (mirror, hinged)

$ =,115.00

605 Aft =avatory Vanity

$ =3,860.00

606 Potty Seat & Shroud (split, cavity)

$ =,490.00

611 Aft =avatory R/H Closet (toilet paper)

$ =,071.00

814 110 =AC Outlets (fwd crew galley)

$ =,761.00

815 =ighting System

$ =,740.00

829 =ngineering / Certification / structural & elect.

$ =5,490.00

$ 251,310.00

options

Options 1

Bid Price

809 Metal Plating

$ 56,470.00

Options 2

Bid Price

405 =nner Window Shades

$ =8,640.00

Options 3

Bid Price

813 USB Ports

$ 10,840.00

Options 4

Bid Price

420 Cabin Single Seats

$ 27,610.00

On May 22, 2017, at 1:06 PM, Eric Roth ███████████████ =rote:

Richard,

I believe there may have =een a mistake in the original break out number we provided.

As you can see below, =fter initially discounting the cost per seat from Rev 2 to Rev 3, I =ave held the cost per seat consistent- inclusive of all changes.

This aside, Jeffrey makes =ontinuous changes, so we are always shooting at a moving target.

No. of =eats	Price	=nbsp;	&n=sp;	Per Seat =		Proposal =evision
-6-	=nbsp;	&n=sp;	=104,560	$17,427	&nb=p;	Rev 2
-8-	=nbsp;	&n=sp;	=122,106	$15,263	&nb=p;	Rev 3

9

-6-	=nbsp;	&n=sp; =91,580	&=bsp; $15,263	&nb=p; Rev 4
-6-	=nbsp;	&n=sp; =91,580	&=bsp; $15,263	&nb=p; Rev 5
-8-	=nbsp;	&n=sp; =122,106	$15,263	&nb=p; Rev 6

Best Regards,

Eric

ERIC H. =OTH | PRESIDENT

<image007.jpg>

██████████████████████████████████ | www.intljet.com
<http://www.intljet.com/> <image008.jpg> <http://twitter.com/#!/intljet> <image009.jpg>

- = - = - - - - -

2221 Smithtown Avenue, Long Island MacArthur =irport, Ronkonkoma, New York 11779

From: Richard Kahn [████████████████████████]
Sent: Monday, May 22, 2017 11:47 AM
To: Eric Roth ██████████████████████████>
Subject: seat prices

In reviewing last few versions of =id i noticed that the seat prices keep changing in Main Cabin Area
=420)

Original quote had 8 seats in the =ain cabin area for $116,800 which is $14,600 per seat

Latest quote dated 5-19-2017 now =as 8 seats for $122,106 which is $15,263.25 per seat

I am not sure what caused this =rice increase as i know JEE originally talked about suede and or =ashmere

Now I understand current path is =eather (2006 bentley color) which i understand to less expensive than =revious two choices

Please advise

Thank you

=

Richard=Kahn
HBRK Associates Inc.
575 Lexington Avenue 4th Floor
New York, NY 10022

=