From: Larry Visoski - ████████████████

Sent: Monday, November 4, 2013 8:15 PM

To: Je vacation

Subject: Update

We found the outflow valves sticks due to overspray paint. Mostly from full o=en to close. It's best to address the outflow valve cleaning while in Teter=oro this week. Avionics is going to Accomplish their functional checks of p=essurization controller tonight.

What is your estimated departure time for tomorrow? So I can make sure plane=is ready.

Thx
Larry

Sent from my iPhone=?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN"
"http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
        <key>date-last-viewed</key>
        <integer>0</integer>
        <key>date-received</key>
        <integer>1383596106</integer>
        <key>flags</key>
        <integer>8590195717</integer>
        <key>gmail-label-ids</key>
        <array>
                <integer>27</integer>
                <integer>7</integer>
        </array>
        <key>remote-id</key>
        <string>359033</string>
</dict>
</plist>