From:	Larry Visoski ██████████
Sent:	Monday, December 1, 2014 6:43 PM
To:	Je vacation
Subject:	727

Appears we found the problem, 35° temp sensor, was also the problem of y=u hearing ice pellets traveling through the air ducks on take off,

okay you were right!!

Sent from my iPhone

```
=?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN"
"http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
        <key>date-last-viewed</key>
        <integer>0</integer>
        <key>date-received</key>
        <integer>1417459392</integer>
        <key>flags</key>
        <integer>8590195713</integer>
        <key>gmail-label-ids</key>
        <array>
                <integer>7</integer>
        </array>
        <key>remote-id</key>
        <string>460247</string>
</dict>
</plist>
```