
From: Larry Visoski lvisoski@delco.com
Sent: Monday, September 11, 2017 10:48 AM
To: Eric Roth; Jay Massar; Je vacation
Subject: G550 #1
Attachments: 819C4D34-70A0-402A-971B-DFE218CAEA54.JPG; Untitled attachment 00004.txt; 94D4FFDF-6708-444D-B8A9-DC41A2ED3FEF.JPG; Untitled attachment 00007.txt; 211C8CED-28D2-4746-8D25-9F9D9858D5C1.JPG; Untitled attachment 00010.txt; 0CD855BE-438E-4F0D-B541-02DAE61A9538.JPG; Untitled attachment 00013.txt; EF3196A9-E40A-432E-B126-567D3B179797.JPG; Untitled attachment 00016.txt; ADF3B131-BCEE-4F6C-90D8-F265783C7AC9.JPG; Untitled attachment 00019.txt; 62E05131-3A75-4452-8319-423A7FE5A535.JPG; Untitled attachment 00022.txt; B38F1285-FE43-4043-9FC9-A20B7BAA1F37.JPG; Untitled attachment 00025.txt

Eric and Jay,

Below are photos with change order from JE for your Mon morning meeting in regards to G550.,

We will arrive Wed at 8am, pls advise what work can be accomplished.

Thx, Larry

Reminder Message from JEE:

90 percent right. most work really great some ,unfortunatley mostly my fault - bad. some ,(divan) others just overlooked . fyi it appears temp fan in back got disconnected, hot in cabin over the atlantic, not much fan. but .. it happens.

1. the sides of the cabin door in front are two different colors. ? very=ugly
- 2 IPhone charger not good for flying. not solid. Shakes,
- 3 I suggest we inset leather on drink rails, cover cup holders and make them smaller. for voss. and find magnetic charger so phone is secure.
4. my captain chair needs a side pouch low hidden for glasses and pens. we might make the arms wider on just this chair
5. footrests. need adjustment , they are currently useless. we should make a small ottoman.
6. Pronto remote works well and should be installed in place of small screen=behind the panels on the window line.
7. the table mechanism needs to be re-cut. Some magnets taken out. and stiffened where it meets the vertical panel. which had a lot of rattles larr= has video
- 8 . I think we should put a stictch on the leather insert tray table tops. they look a little like placemats. without
9. the Pilots seat arm rest needs more foam on top arm rest to be taller, Pilot's arm does not reach the arm rest, even when extended to tallest position= maybe wider foam arm rest as well, so when stored they don't shake/Rattle,=and taller/thicker foam to meet pilots arm.,
10. the chairs in the cabin were shaking quite a bit on take off
11. the psu in the galley which looks great should be changed to white and make down wash lights installed.
12. credenz top should be white to match the galley, and seats like the GIV.=
13. we should cover aft bulkhead and lav door with fabric
14. many of the doors and latches were rattling
15. shelf for food storage with proper size top opening bag.
16. In rear LAV the entrance to Baggage compartment has a Head Bumper over the baggage door we left the old leather, change to white.
17. the psu over the sink should be white and cut back and made shorter, I kept banging my head when brushing my teeth
- 18 some type of cover for toilet paper
19. more cushion on potty seat. PLENTY of room
- 20 new potty seat. not nice
21. L/H Rear bulkhead Aft magazine holder that houses Aft Cabin Temp fan should be covered as well in fabric.

22. bag carrier should have higher sides to lay down books
- 23 . lets recover the two front seats in fabric
24. biggest is the DIVAN . almost nothing right. . arms should be higher=and either fabric and soft to lean on, they should extend if possible to the out board wall. the fabric and welting does not look good on the seat cushion , it is deformed, I took photos.? the rear cushions are much too hard. angled incorrectly and the Piping/welting was put on the front side instead of the back. you and I were worried about the corner when you sat back=on them. . when made into a bed, the drink rail is exposed, and rough =we need to rethink the whole.
25. there is a light on in the under the VIP bathroom cabinet by the floor that I cant turn off.
26. some of the switches need to be changed, they are old and rattle, same for some latches.
27. the new wood covered glassware covered rattled like crazy on take off. = putty on the sides of the outboard?
- 28 it is going to be great. . the divan arms look too bulky and hard maybe cashmere arms with foam. not sure
- 29 odd -but some chair cushions are different than others. i measured. ?= i kept switching them around
30. Leather arm rest covers like GIV?

Photos

1-Need Better way to lift the tray table,. Maybe cut a groove where His index=finger is currently, to grasp with his finger, difficult to raise table when stored,