
From: ZM [REDACTED]
Sent: Thursday, June 1, 2017 2:35 AM
To: jeffrey E.
Subject: Re: ZM Mercedes S500

Ok

Sent from my iPhone

On May 31, 2017, at 7:27 PM, jeffrey E. <jeevacation@gmail.com <mailto:jeevacat=on@gmail.com> > wrote:

reman

On Wed, May 31, 2017 at 9:18 PM, Brice Gor=on [REDACTED] > wrote:

=effrey

Mercedes of ABQ are=having difficulty obtaining Transmission module

options are:

1. OEM Part Germany,- Back Order, \$953.70, unable to c=nfirm delivery
2. Remanufactured Part from CA, \$1683.00, 3 d=ys

how do you wish to proceed,

regar=s Brice

On Tue, May 23, 2017 at 10:31 AM, jeff=ey E. <jeevacation@gmail.com <mailto:jeevacation@gmail.com> > wrote:

Ok

On Tue, May 23, 2017 at 12:23 PM Brice Gordon [REDACTED]
<m [REDACTED]> wrote:

Jeffrey

attached Video and Repair estimate for your reference <=div>

During the final inspection of the Mercedes S 500, the Technician discovered found oil and water contamination in the Transmission control unit. This is due to failed Electronic connector at the Transmission

Total Cost of repairs, as of date, including the above, less tax \$8297.87

Do you wish to proceed with repair?

80 regards

Brice Gordon
Stanley, NM

Ph: [REDACTED] e=>

--

Brice Gordon
Stanley, NM

[REDACTED]

--

= please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for

the use of the addressee. It is the property of JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this

communication in error please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

"