
From: Brice Gordon [REDACTED]
Sent: Thursday, June 1, 2017 1:19 AM
To: jeffrey E.
Subject: Re: ZM Mercedes S500

Jef=rey

=div class="gmail_default" style="font-size:small">Mercedes of ABQ are =aving difficulty obtaining Transmission module options are:

1. OEM Part Germany, - Back Order, \$953.70, unable=to confirm delivery
2. Remanufactured Part from CA, \$1683.=0, 3 days

how do you wish to proceed,

regards Brice

On Tue, May 23, 2017 at 10:=1 AM, jeffrey E. <jeevacation@gmail.com <mailto:jeevacation@gmail.com>> wrote:

Ok

On Tue, May 23, 2017 at 12:23 PM Brice Gordon [REDACTED]

Jeffrey

attached Video and Repair estimate for your reference =/div>

During the final inspect=on of the Mercedes S 500, the Technician discovered found oil and water co=tamination in the Transmission control unit. This is due to failed Electron=c connector at the Transmission

The cost to repair will be an additional \$1447.879

Total Cost of repairs, as of date, including the a=ove, less tax \$8297.87

Do you wish to proceed with repair?

regards

Brice Gordon
Stanley, NM

-->_driv>

--
=C2◆ please note

The information contained in this co=munication is
confidential, may be attorney-client privileged, may
c=nstitute inside information, and is intended only for
the use of the ad=ressee. It is the property of

JEE

Unauthorized use, disclosure or co=ying of this
communication or any part thereof is strictly prohibitedand may be unlawful. If you have received this
communication in error,=please notify us immediately by
return e-mail or by e-mail to jeevacation@gmail.com</=>, and
destroy this communication and all copies thereof,
including =ll attachments. copyright -all rights reserved

--
Brice Gordon
Stanley, NM