
From: Larry Visoski <[REDACTED]>
Sent: Wednesday, November 4, 2015 2:39 PM
To: Je vacation
Subject: Fuel

Jeffrey

We removed the fwd panel by landing light lens,, no obvious source of leak. P=te will remove filet panel upper portion of wing to Fusalge,, appears fuel is coming from upper portion of wing under fuselage. This Will be time consuming repair locating its source.

Fuel leak has slowed to a drip every 2 to 3 seconds now. Still shouldn't leak,. Gulfstream maintenance Manuel allows a one drip per 30 seconds.

Bill would arrive Palm beach at 6pm tonight, -Should Dave and I head to PBI now and bring Boeing to Newark tonight?

Thx
Larry

Sent from my iPhone=?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN"
"http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
 <key>date-last-viewed</key>
 <integer>0</integer>
 <key>date-received</key>
 <integer>1446648221</integer>
 <key>flags</key>
 <integer>8590195713</integer>
 <key>gmail-label-ids</key>
 <array>
 <integer>5</integer>
 </array>
 <key>remote-id</key>
 <string>560235</string>
</dict>
</plist>