
From: [REDACTED]
Sent: Friday, March 4, 2011 7:43 AM
To: Je vacation
Subject: Apu

We took cannon plug apart and found soldered wires in stead of crimped, so simple fix only required re-soldering of wires, no need for new cannon plug, so we should be able to complete paper work, one more functional check in the morning and ready for departure, I'd say 11am would be a safe time for return to service.

Thx,

Larry

Sent via BlackBerry by AT&T

```
<?xml version="1.0" encoding="UTF-8"?>
```

```
<!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
```

```
<plist version="1.0">
```

```
<dict>
```

```
  <key>date-last-viewed</key>
```

```
  <integer>0</integer>
```

```
  <key>date-received</key>
```

```
  <integer>1299224570</integer>
```

```
  <key>flags</key>
```

```
  <integer>8590195713</integer>
```

```
  <key>gmail-label-ids</key>
```

```
  <array>
```

```
    <integer>5</integer>
```

```
    <integer>18</integer>
```

```
  </array>
```

```
  <key>original-mailbox</key>
```

```
  <string>imap://jeevacation@imap.gmail.com/%5BGmail%5D/All%20Mail</string>
```

```
  <key>remote-id</key>
```

```
  <string>139150</string>
```

```
</dict>
```

```
</plist>
```