

---

**From:** Larry Visoski <[REDACTED]>  
**Sent:** Wednesday, January 18, 2017 8:40 PM  
**To:** Je vacation  
**Subject:** Water separator  
**Attachments:** IMG\_0105.JPG; Untitled attachment 00076.txt; IMG\_0104.JPG; Untitled attachment 00079.txt; IMG\_0106.JPG; Untitled attachment 00082.txt

Corroded and pitted water separator housing cone photo below needs new,, Sock in photo below goes over the outside of the water separator Cone,, we will also change the sock as well.,.  
Both sides need replace.