
From: Larry Visoski <[REDACTED]>
Sent: Thursday, November 5, 2015 4:40 PM
To: Jeffrey
Subject: Je vacation
Update

Jeffrey

Here is the Plan.,

Gulfstream is going to address every leak possible.

Some will require changing High Lock, other is removing all sealant by wing a=tach pins that penetrate fuel tank and apply new sealant., Time frame for return to service 3 days give or take 1 day, is realistic. They'll apply new sealant, and install high locks, allow sealant to cure overnight and re-fuel to max and re-check for leaks.

Return to service Sunday is the plan.

Thx

Larry

Sent from my iPhone=?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN"

"http://www.apple.com/DTDs/PropertyList-1.0.dtd">

<plist version=.0">

<dict>

 <key>date-last-viewed</key>

 <integer>0</integer>

 <key>date-received</key>

 <integer>1446741611</integer>

 <key>flags</key>

 <integer>8590195713</integer>

 <key>gmail-label-ids</key>

 <array>

 <integer>18</integer>

 <integer>5</integer>

 </array>

 <key>remote-id</key>

 <string>560582</string>

</dict>

</plist>