

---

**From:** Larry Visoski [REDACTED]  
**Sent:** Monday, September 4, 2017 8:09 PM  
**To:** jeffrey E.  
**Subject:** Re:

I thought the same thing,,  
Not really,, I have photos of the pressurization Pa=e in April with PAC temp pressure reading 40 degrees,. Which is a normal reading,. Outside air temperature/ISA has an effect on temperature performance so it does vary,. This flight we had R/H PAC temp reading of 80,.&nbs=;

Thx  
Larry

Sent from my iPhone

On Sep 4, 2017, at=10:06 PM, jeffrey E. <jeevacati=n@gmail.com <mailto:jeevacation@gmail.com> > wrote:

is there a reason that such a worn valve was not picked up in p=e buy?

--

&nbs=; please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee= It is the property of JEE

Unauthorized use, disclosure or copying of= this communication or any part thereof is strictly prohibited and may=be unlawful. If you have received this communication in error, please no=ify us immediately by return e-mail or by e-mail to jeevacation@gmail.com <mailto:je=vacation@gmail.com> , and destroy this communication and all copies thereof, including all attachments= copyright -all rights reserved

=