

---

**From:** Ann Rodriguez [REDACTED]  
**Sent:** Friday, November 6, 2015 12:20 AM  
**To:** jeffrey E.  
**Cc:** Richard Kahn; Zorro Ranch  
**Subject:** Transformer: Mr. Felix Rey

----- Forwarded message -----

From: Felix S. Rey [REDACTED]  
Date: Thu, Nov 5, 2015 at 5:04 PM  
Subject: RE: LSJE, LLC - November 5, 2015  
To: Daphne Wallace [REDACTED]

The 1500kva transformer was tested with TTR test. The B bushing on the transformer tested good but with high amps. The A bushing was tested and the D tap for that side of the transformer failed. We believe the 1500kva is much too large a transformer for the load that the island is using. Your meter at the site is showing less than 200amps per phase. A 500kva is more a better size for the island at this point. As for the meter base we are still trying to get one.