
From: Ann Rodriguez <[REDACTED]>
Sent: Monday, July 13, 2015 7:45 PM
To: jeffrey E.
Cc: Rich Kahn
Subject: Fwd: Big N

Ann R.

Begin forwarder= message:

From: gene kra= <[REDACTED]> &g=;
Date: July 13, 2015 at 2:45:52 PM AST
To: Ann Rodriqu=z <[REDACTED]> &=t;, Debra Lowry
<[REDACTED]>
Subject: Big N
Reply-To:<=b> gene kral <[REDACTED]>

=/div>

I came back o= Island today and reviewed progress on Big ,all looks great and I'm please&=bsp;with progress.
A decision needs to be made on the fuel tanks. At this time the tanks a=e not leaking but will in the near future.
After extensive cleaning the bot=om of the tank has many large pits that will soon start to leak.

=div id="yui_3_16_0_1_1436474794660_319893" dir="ltr">The condition of t=e tanks most likely were caused by not having a proper sealing of the deck f=el fitting allowing salt water to enter the tank and do its damage.

These fittings were p=aced on the deck ,in our quote we would have a stand pipe above the d=ck next to the wheel house so this problem will not happen again. = We will need a answer soon so work will not be delayed any longer than nec=ssary.

<=div>

Please v=sit or call with any concerns.

Thanks

Gene

Gene Kral Sr. <=r>Subbase Drydock, Inc.

Parcel 162, Subbase

St. Thomas, USVI 00802 <=r>TEL: [REDACTED]

FAX: [REDACTED]

www.subbasedrydock.com <http://www.subb=sedrydock.com>

</=lockquote>

=