
From: Lvjet <[REDACTED]>
Sent: Thursday, January 9, 2014 4:57 AM
To: jeevacation@gmail.com
Subject: mounts

Jeffrey,
My records indicate Fwd mounts have been changed Dec 15, 2008 during engine overhaul,.
The L/H and R/H Aft mounts were changed in 1998 according to CMP report below,,.
total time at this time: 8643

<https://cmp.mygulfstream.com/Images/minus.gif> 712061 (P) Airframe Vibration
Isolator (Left Forward Mount, Forward) - Removal / Installation
P/N: 94756-04 S/N: 5541 MAN <https://cmp.mygulfstream.com/images/dotGreen.gif> Part
= Event Category
Part (P) PN 94756-04 Enter Part Number
C/W
Hrs: 7178.6
Lnd: 3292
Date: 15 Dec 2008

Freq [javascript:openCustomFreq\(3415926\);](#)
SN
Mfg Ref Number: 71-01-00
Doc: GIV AMM Rev: 3 Issued: 3 Sep 2012
Section:
[select name="DocLinks" style="width: 180px; font-family: arial; font-size: 8pt;">Documents](#)AMM 712061Task=20
Card [javascript:openComplImageLoader\('3415926'\)](#) Watched Ops Package Last Updated By: Rick Reynolds Date:
06 Dec 2012 13:15 Est. Parts/Labor: \$0.00/0.00 Hrs.
<https://cmp.mygulfstream.com/C=mppliance/BudgetEstimate.aspx?ataNumber=712061> OEM Labor Hours:4.0
Mx. Notes: Special Notation: Show Related Codes Show Part Detail Show C/W Adjustments

C/W Adjustments

iframe Time used for Due Calculation ☒

Hours:	Initial Frequency:	N/A
Cycles:	Recurring Frequency:	N/A Next due was not adjusted.
Date:	Frequency Tolerance:	N/A

=input name="currentHoursComponent" type="hidden" value="8638.600"> <=nput name="currentCyclesComponent" type="hidden" value="4005.000"> <=nput name="isPartRel" type="hidden" value="1">

Part Details

Manufac=urer: Install=20 Status: RB - RebuiltR - RepairedI - InspectedM - ModifiedN - NewO -
Overhauled Current Part Run Time: Hours Landings Months

TSN

TSO

TSR

Vendor:=nbsp; Mod Sta=us:

HW Vers=on: Part Warranty:

SW Vers=on: Labor=20 Warranty:

Maint T=g: Airframe Time =t Install

Hours:

Cycles:

Date:

Part Time at=20 Install

Hours Cycles [=onths or Date]

TSN: <javascript:doNothing();> </=> <javascript:doNothing();>

TSR: <javascript:doNothing();> <=td>

New Cos=: \$1,750.34

Overhau=ed:

Repaire=:

OEM Ven=or: BARRY CONTROLS AEROSPACE Install=20 Notes: ATA 712061 Compliance History

Part ON # Serial ON # CW Hrs CW Cyc CW Date Actual Cost Work Order #

Part OFF # Serial OFF # Remark / Malfunction Actual Labor Facility

94756-04 ON : 5541 7,178.6 3,292 15 Dec 2008 0.00 [view]

<javascript:openComplHistE=itor('3415926', 18903364)>

<javascript:openCompHistImageLoader('3415926','18903364')>

OFF: 0.00

94756-04 ON : 3,601.0 1,644 11 Dec 1998 0.00 [view] <javascript:openComplHistE=itor('3415926', 1306914)>

<javascript:openCompHistImageLoader('3415926','1306914')>

OFF: 0.00 GAC-APP

ON : 94756-04 ON : 0.0 0 07 Dec 1988 0.00 [view]

<javascript:openComplHistE=itor('3415926', 5283603)>

<javascript:openCompHistImageLoader('3415926','5283603')>

0.00

=/div>

<https://cmp.mygulfstream.com/Images/minus.gif> 712062 (P)

Airframe

Vibration

Isolator (Left Forward Mount, A=t) - Removal / Installation

P/N: 94756-04 S/N: 5537

MAN <https://cmp.mygulfstream.com/images/dotGreen.=if> Part

= Event Category

Part (P) PN 94756-04 Enter Part Number

C/W

Hrs: 7178.6

Lnd: 3292

Date: 15 Dec 2008

Freq <javascript:op=nCustomFreq(3414655);>

SN

Mfg Ref Number: 71-01-00

Doc: GIV AMM Rev: =3 Issued: 3= Sep 2012

Section:

<=elect name="DocLinks" style="width: 180px; font-family: arial; font-si=e: 8pt;">DocumentsAMM 712061Task=20

Card <javascript:openComplImageLoader('3414655')> Watched Ops Package Last Upd=ted By: Rick Reynolds Date:

06=Dec 2012 13:18 Est. =arts/Labor: \$0.00/0.00 Hrs.

<https://cmp.mygulfstream.com/C=mpliance/BudgetEstimate.aspx?ataNumber=712062> OEM Labor Hours:4.0

Mx. Notes: Special Notation: Show Related=Codes Show Part Detail= S=ow C/W Adjustments

C/W Adjustments=/span>

=iframe Time used for Due Calculation =input name="opsSpec" id="opsSpec" type="checkbox" checked=""

value=3D"on">Ops Spec

Hours: Initial Frequency: N/A

Cycles: Recurring Frequency:<=font> N/A Next due was not adjusted. <=tr>

Date: Frequency Tolerance:<=font> N/A

=input name="currentHoursComponent" type="hidden" value="8638.600"> <=nput name="currentCyclesComponent"

type="hidden" value="4005.000"> <=nput name="isPartRel" type="hidden" value="1">

Part Details

Manufac=urer: Install=20 Status: RB - RebuiltR - RepairedI - InspectedM - ModifiedN - NewO -

Overhauled Current Part Run Time: Hours Landings Months

TSN

TSO

TSR

Vendor:=nbsp; Mod Sta=us:

HW Vers=on: Part Warranty:

SW Vers=on: Labor=20 Warranty:

Maint T=g: Airframe Time =t Install

Hours:

Cycles:

Date:

Part Time at=20 Install

Hours Cycles [=onths or Date]

TSN: <javascript:doNothing();> </=> <javascript:doNothing();>

TSR: <javascript:doNothing();> <=td>

New Cos=: \$1,750.34

Overhau=ed:

Repaire=:

OEM Ven=or: BARRY CONTROLS AEROSPACE Install=20 Notes: MAN

<https://cmp.mygulfstream.com/images/dotGreen.=if> Part

= Event Category

Part (P) PN 94756-94756-13 Enter Part Number

C/W

Hrs: 3601.0

Lnd: 1644

Date: 11 Dec 1998

Freq <javascript:op=nCustomFreq(3417398);>

SN

Mfg Ref Number: 71-01-00

Doc: GIV AMM Rev: =3 Issued: 3= Sep 2012

Section:

<=elect name="DocLinks" style="width: 180px; font-family: arial; font-size: 8pt;">DocumentsAMM 712061Task=20
Card <javascript:openComplImageLoader('3417398')> Watched Ops Package Last Updated By: Rick Reynolds Date:
06=Dec 2012 13:21 Est. =arts/Labor: \$0.00/0.00 Hrs.
<https://cmp.mygulfstream.com/C=mppliance/BudgetEstimate.aspx?ataNumber=712063> OEM Labor Hours:4.0
Mx. Notes: FREQ DETERMINED BY P/N Special Notation: Show Related=Codes Show Part Detail=
S=ow C/W Adjustments

C/W Adjustments=

=iframe Time used for Due Calculation =input name="opsSpec" id="opsSpec" type="checkbox" checked=""
value=3D"on">Ops Spec

Hours: Initial Frequency: N/A

Cycles: Recurring Frequency:<=font> N/A Next due was not adjusted. <=tr>

Date: Frequency Tolerance:<=font> N/A

=input name="currentHoursComponent" type="hidden" value="8638.600"> <=nput name="currentCyclesComponent"
type="hidden" value="4005.000"> <=nput name="isPartRel" type="hidden" value="1">

Part Details

Manufac=urer: Install=20 Status: RB - RebuiltR - RepairedI - InspectedM - ModifiedN - NewO -
Overhauled Current Part Run Time: Hours Landings Months

TSN

TSO

TSR

Vendor:=nbsp; Mod Sta=us:

HW Vers=on: Part Warranty:

SW Vers=on: Labor=20 Warranty:

Maint T=g: Airframe Time =t Install

Hours:

Cycles:

Date:

Part Time at=20 Install

Hours Cycles [=onths or Date]

TSN: = <javascript:doNothing();> </=> <javascript:doNothing();>

TSR: <javascript:doNothing();> <=td>

New Cos=: \$1,747.28

Overhau=ed:

Repaire=:

OEM Vendor: BARRY CONTROLS AEROSPACE Install=20 Notes: MAN

<<https://cmp.mygulfstream.com/images/dotGreen.gif>> Part

= Event Category

Part (P) PN 13636-94756-0394756-13 Ent=r Part Number

C/W

Hrs: 3601.0

Lnd: 1644

Date: 11 Dec 1998

Freq <javascript:openCustomFreq(3417344);>

SN

Mfg Ref Number: 71-01-00

Doc: GIV AMM Rev: =3 Issued: 3= Sep 2012

Section:

<=elect name="DocLinks" style="width: 180px; font-family: arial; font-size: 8pt;">DocumentsAMM 712061Task=20

Card <javascript:openComplImageLoader('3417344')> Watched Ops Package Last Updated By: Rick Reynolds Date:

06=Dec 2012 13:23 Est. =arts/Labor: \$0.00/0.00 Hrs.

<<https://cmp.mygulfstream.com/C=pliance/BudgetEstimate.aspx?ataNumber=712064>> OEM Labor Hours:4.0

Mx. Notes: FREQ DETERMINED BY P/N Special Notation: Show Related=Codes Show Part Detail=

Show C/W Adjustments

C/W Adjustments=

=iframe Time used for Due Calculation =input name="opsSpec" id="opsSpec" type="checkbox" checked=""

value=3D"on">Ops Spec

Hours: Initial Frequency: N/A

Cycles: Recurring Frequency:<=font> N/A Next due was not adjusted. <=tr>

Date: Frequency Tolerance:<=font> N/A

=input name="currentHoursComponent" type="hidden" value="8638.600"> <=nput name="currentCyclesComponent"

type="hidden" value="4005.000"> <=nput name="isPartRel" type="hidden" value="1">

Part Details

Manufacturer: Install=20 Status: RB - RebuiltR - RepairedI - InspectedM - ModifiedN - NewO -

Overhauled Current Part Run Time: Hours Landings Months

TSN

TSO

TSR

Vendor:=nbsp; Mod Sta=us:

HW Version: Part Warranty:

SW Version: Labor=20 Warranty:

Maint T=g: Airframe Time =t Install

Hours:

Cycles:

Date:

Part Time at=20 Install

Hours Cycles [=onths or Date]

TSN: = <javascript:doNothing();> </=> <javascript:doNothing();>

TSR: <javascript:doNothing();> <=td>

New Cos=: \$1,747.28

Overhaul=ed:

Repaired=:

OEM Vendor: BARRY CONTROLS AEROSPACE Install=20 Notes: ATA 712064 Compliance History

Part ON # Serial ON # CW Hrs CW Cyc CW Date Actual Cost Work Order #

Part OFF # Serial OFF # Remark / Malfunction Actual Labor Facility

ON : 94756-13 ON : 2982 3,601.0 1,644 11 Dec 1998 0.00 [view]

<javascript:openCompHistE=itor('3417344', 2664578)>

<javascript:openCompHistImageLoader('3417344',='2664578')>

OFF : 13636-94756-03 OFF: 0521 0.00 GAC-APP

ON : 13636-94756-03 ON : 0521 0.0 0 07 Dec 1988 0.00 [view]

<javascript:openCompHistE=itor('3417344', 5751294)>

<javascript:openCompHistImageLoader('3417344',='5751294')>

0.00

=/div>

<https://cmp.mygulfstream.com/Images/minus.gif> 712065 (P)

Airframe

Vibration

Isolator (Right Forward Mount, Forward) - Removal / Installation

P/N: 94756-04 S/N: 5536

MAN <https://cmp.mygulfstream.com/images/dotGreen.=if> Part

= Event Category

Part (P) PN 94756-04 Enter Part Number

C/W

Hrs: 7178.6

Lnd: 3292

Date: 15 Dec 2008

Freq <javascript:openCustomFreq(3417286);>

SN

Mfg Ref Number: 71-01-00

Doc: GIV AMM Rev: =3 Issued: 3= Sep 2012

Section:

<=elect name="DocLinks" style="width: 180px; font-family: arial; font-size: 8pt;">DocumentsAMM 712061Task=20

Card <javascript:openCompImageLoader('3417286')> Watched Ops Package Last Updated By: Rick Reynolds Date:

06=Dec 2012 13:26 Est. =arts/Labor: \$0.00/0.00 Hrs.

<https://cmp.mygulfstream.com/C=pliance/BudgetEstimate.aspx?ataNumber=712065> OEM Labor Hours:4.0

Mx. Notes: Special Notation: Show Related=Codes Show Part Detail= Show C/W Adjustments

C/W Adjustments=

=iframe Time used for Due Calculation =input name="opsSpec" id="opsSpec" type="checkbox" checked=""

value=3D"on">Ops Spec

Hours: Initial Frequency: N/A

Cycles: Recurring Frequency:<=font> N/A Next due was not adjusted. <=tr>

Date: Frequency Tolerance:<=font> N/A

=input name="currentHoursComponent" type="hidden" value="8638.600"> <=nput name="currentCyclesComponent" type="hidden" value="4005.000"> <=nput name="isPartRel" type="hidden" value="1">

Part Details

Manufac=urer: Install=20 Status: RB - RebuiltR - RepairedI - InspectedM - ModifiedN - NewO -
Overhauled Current Part Run Time: Hours Landings Months

TSN

TSO

TSR

Vendor:=nbsp; Mod Sta=us:

HW Vers=on: Part Warranty:

SW Vers=on: Labor=20 Warranty:

Maint T=g: Airframe Time =t Install

Hours:

Cycles:

Date:

Part Time at=20 Install

Hours Cycles [=onths or Date]

TSN: <javascript:doNothing();> </=> <javascript:doNothing();>

TSR: <javascript:doNothing();> <=td>

New Cos=: \$1,750.34

Overhau=ed:

Repaire=:

OEM Ven=or: BARRY CONTROLS AEROSPACE Install=20 Notes: ATA 712065 Compliance History

Part ON # Serial ON # CW Hrs CW Cyc CW Date Actual Cost Work Order #

Part OFF # Serial OFF # Remark / Malfunction Actual Labor Facility

94756-04 ON : 5536 7,178.6 3,292 15 Dec 2008 0.00 [view]

<javascript:openComplHistE=itor('3417286', 18903366)>

<javascript:openCompHistImageLoader('3417286','18903366')>

OFF: 0.00

94756-04 ON : 3,601.0 1,644 11 Dec 1998 0.00 [view] <javascript:openComplHistE=itor(

'3417286', 1372783)>

<javascript:openCompHistImageLoader('3417286','1372783')>

OFF: 0.00 GAC-APP

ON : 94756-04 ON : 0.0 0 07 Dec 1988 0.00 [view]

<javascript:openComplHistE=itor('3417286', 5308553)>

<javascript:openCompHistImageLoader('3417286','5308553')>

0.00

=/div>

<https://cmp.mygulfstream.com/Images/minus.gif> 712066 (P)

Airframe Vibration

Isolator (Right Forward Mount, =ft) - Removal / Installation

P/N: 94756-04 S/N: 5538 MAN <https://cmp.mygulfstream.com/images/dotGreen.=if> Part

= Event Category

Part (P) PN 94756-04 Enter Part Number

C/W

Hrs: 7178.6

Lnd: 3292

Date: 15 Dec 2008

Freq <javascript:op=nCustomFreq(3417626);>

SN

Mfg Ref Number: 71-01-00

Doc: GIV AMM Rev: =3 Issued: 3= Sep 2012

Section:

<=elect name="DocLinks" style="width: 180px; font-family: arial; font-si=e: 8pt;">DocumentsAMM 712061Task=20

Card <javascript:openComplImageLoader('3417626')> Watched Ops Package Last Upd=ted By: Rick Reynolds Date:

06=Dec 2012 13:29 Est. =arts/Labor: \$0.00/0.00 Hrs.

<https://cmp.mygulstream.com/C=mpliance/BudgetEstimate.aspx?ataNumber=712066> OEM Labor Hours:4.0

Mx. Notes: Special Notation: Show Related=Codes Show Part Detail= S=ow C/W Adjustments

C/W Adjustments=/span>

=iframe Time used for Due Calculation =input name="opsSpec" id="opsSpec" type="checkbox" checked=""

value=3D"on">Ops Spec

Hours: Initial Frequency: N/A

Cycles: Recurring Frequency:<=font> N/A Next due was not adjusted. <=tr>

Date: Frequency Tolerance:<=font> N/A

=input name="currentHoursComponent" type="hidden" value="8638.600"> <=nput name="currentCyclesComponent"

type="hidden" value="4005.000"> <=nput name="isPartRel" type="hidden" value="1">

Part Details

Manufac=urer: Install=20 Status: RB - RebuiltR - RepairedI - InspectedM - ModifiedN - NewO -

Overhauled Current Part Run Time: Hours Landings Months

TSN

TSO

TSR

Vendor:=nbsp; Mod Sta=us:

HW Vers=on: Part Warranty:

SW Vers=on: Labor=20 Warranty:

Maint T=g: Airframe Time =t Install

Hours:

Cycles:

Date:

Part Time at=20 Install

Hours Cycles [=onths or Date]

TSN: <javascript:doNothing();> </=> <javascript:doNothing();>

TSR: <javascript:doNothing();> <=td>

New Cos=: \$1,750.34

Overhau=ed:

Repaire=:

OEM Ven=or: BARRY CONTROLS AEROSPACE Install=20 Notes: ATA 712066 Compliance History

Part ON # Serial ON # CW Hrs CW Cyc CW Date Actual Cost Work Order #

Part OFF # Serial OFF # Remark / Malfunction Actual Labor Facility

94756-04 ON : 5538 7,178.6 3,292 15 Dec 2008 0.00 [view]

<javascript:openCompHistE=itor('3417626', 18903367)>
 <javascript:openCompHistImageLoader('3417626','18903367')>
OFF: 0.00

94756-04 ON : 3,601.0 1,644 11 Dec 1998 0.00 [view] <javascript:openCompHistE=itor('3417626', 1874829)>

 <javascript:openCompHistImageLoader('3417626','1874829')>
OFF: 0.00 GAC-APP

ON : 94756-04 ON : 0.0 0 07 Dec 1988 0.00 [view]

<javascript:openCompHistE=itor('3417626', 5478663)>
 <javascript:openCompHistImageLoader('3417626','5478663')>
 0.00

=/div>

 <https://cmp.mygulfstream.com/Images/minus.gif> 712067 (P) Airframe Vibration
Isolator (Right Aft Mount, Forw=rd) - Removal / Installation

P/N: 94756-13 S/N: 2993 MAN <https://cmp.mygulfstream.com/images/dotGreen.=if> Part
= Event Category

Part (P) PN 13636-94756-0394756-13 Ent=r Part Number

C/W

Hrs: 3601.0

Lnd: 1644

Date: 11 Dec 1998

Freq <javascript:op=nCustomFreq(3414842);>

SN

Mfg Ref Number: 71-01-00

Doc: GIV AMM Rev: =3 Issued: 3= Sep 2012

Section:

<=elect name="DocLinks" style="width: 180px; font-family: arial; font-si=e: 8pt;">DocumentsAMM 712061Task=20

Card <javascript:openCompImageLoader('3414842')> Watched Ops Package Last Upd=ted By: Rick Reynolds Date:

06=Dec 2012 13:31 Est. =arts/Labor: \$0.00/0.00 Hrs.

<https://cmp.mygulfstream.com/C=mpliance/BudgetEstimate.aspx?ataNumber=712067> OEM Labor Hours:4.0

Mx. Notes: FREQ DETERMINED BY P/N Special Notation: Show Related=Codes Show Part Detail=

S=ow C/W Adjustments

C/W Adjustments=/span>

=iframe Time used for Due Calculation =input name="opsSpec" id="opsSpec" type="checkbox" checked=""
value=3D"on">Ops Spec

Hours: Initial Frequency: N/A

Cycles: Recurring Frequency:<=font> N/A Next due was not adjusted. <=tr>

Date: Frequency Tolerance:<=font> N/A

=input name="currentHoursComponent" type="hidden" value="8638.600"> <=nput name="currentCyclesComponent" type="hidden" value="4005.000"> <=nput name="isPartRel" type="hidden" value="1">

Part Details

Manufac=urer: Install=20 Status: RB - RebuiltR - RepairedI - InspectedM - ModifiedN - NewO -
Overhauled Current Part Run Time: Hours Landings Months

TSN

TSO

TSR

Vendor:=nbsp; Mod Sta=us:

HW Vers=on: Part Warranty:

SW Vers=on: Labor=20 Warranty:

Maint T=g: Airframe Time =t Install

Hours:

Cycles:

Date:

Part Time at=20 Install

Hours Cycles [=onths or Date]

TSN: <javascript:doNothing();> </=> <javascript:doNothing();>

TSR: <javascript:doNothing();> <=td>

New Cos=: \$1,747.28

Overhau=ed:

Repaire=:

OEM Ven=or: BARRY CONTROLS AEROSPACE Install=20 Notes: ATA 712067 Compliance History

Part ON # Serial ON # CW Hrs CW Cyc CW Date Actual Cost Work Order #

Part OFF # Serial OFF # Remark / Malfunction Actual Labor Facility

ON : 94756-13 ON : 2993 3,601.0 1,644 11 Dec 1998 0.00 [view]

<javascript:openComplHistE=itor('3414842', 4484068)>

<javascript:openCompHistImageLoader('3414842','4484068')>

OFF : 13636-94756-03 OFF: 0518 0.00 GAC-APP

ON : 13636-94756-03 ON : 0518 0.0 0 07 Dec 1988 0.00 [view]

<javascript:openComplHistE=itor('3414842', 6381279)>

<javascript:openCompHistImageLoader('3414842','6381279')>

0.00

=/div>

<https://cmp.mygulfstream.com/Images/minus.gif> 712068 (P)

Airframe Vibration

Isolator (Right Aft Mount, Aft)= Removal / Installation

P/N: 94756-13 S/N: 2994 MAN <https://cmp.mygulfstream.com/images/dotGreen.=if> Part

= Event Category

Part (P) PN 13636-94756-0394756-13 Ent=r Part Number

C/W

Hrs: 3601.0

Lnd: 1644

Date: 11 Dec 1998

Freq <javascript:op=nCustomFreq(3415890);>
 SN
 Mfg Ref Number: 71-01-00
 Doc: GIV AMM Rev: =3 Issued: 3= Sep 2012
 Section:
 <=elect name="DocLinks" style="width: 180px; font-family: arial; font-si=e: 8pt;">DocumentsAMM 712061Task=20
 Card <javascript:openComplImageLoader('3415890')> Watched Ops Package Last Upd=ted By: Rick Reynolds Date:
 06=Dec 2012 13:34 Est. =arts/Labor: \$0.00/0.00 Hrs.
 <https://cmp.mygulfstream.com/C=mpliance/BudgetEstimate.aspx?ataNumber=712068> OEM Labor Hours:4.0
 Mx. Notes: Special Notation: Show Related=Codes Show Part Detail= Sow C/W Adjustments

C/W Adjustments=/span>
 =iframe Time used for Due Calculation =input name="opsSpec" id="opsSpec" type="checkbox" checked=""
 value=3D"on">Ops Spec
 Hours: Initial Frequency: N/A
 Cycles: Recurring Frequency:<=font> N/A Next due was not adjusted. <=tr>
 Date: Frequency Tolerance:<=font> N/A
 =input name="currentHoursComponent" type="hidden" value="8638.600"> <=nput name="currentCyclesComponent"
 type="hidden" value="4005.000"> <=nput name="isPartRel" type="hidden" value="1">

Part Details

Manufac=urer: Install=20 Status: RB - RebuiltR - RepairedI - InspectedM - ModifiedN - NewO -
 Overhauled Current Part Run Time: Hours Landings Months

TSN

TSO

TSR

Vendor:=nbsp; Mod Sta=us:
 HW Vers=on: Part Warranty:
 SW Vers=on: Labor=20 Warranty:
 Maint T=g: Airframe Time =t Install

Hours:

Cycles:

Date:

Part Time at=20 Install

Hours Cycles [=onths or Date]

TSN: <javascript:doNothing();> </=> <javascript:doNothing();>

TSR: <javascript:doNothing();> <=td>

New Cos=: \$1,747.28

Overhau=ed:

Repaire=:

OEM Ven=or: BARRY CONTROLS AEROSPACE Install=20 Notes: ATA 712068 Compliance History

Part ON # Serial ON # CW Hrs CW Cyc CW Date Actual Cost Work Order #

Part OFF # Serial OFF # Remark / Malfunction Actual Labor Facility

ON : 94756-13 ON : 2994 3,601.0 1,644 11 Dec 1998 0.00 [view]

<javascript:openComplHistE=itor('3415890', 3700147)>

<javascript:openCompHistImageLoader('3415890','3700147')>

OFF : 13636-94756-03 OFF: 0496 0.00 GAC-APP

ON : 13636-94756-03 ON : 0496 0.0 0 07 Dec 1988 0.00 [view]

<javascript:openCompHistE=itor('3415890', 6087564)>
<javascript:openCompHistImageLoader('3415890',='6087564')>
0.00

=/div>

<https://cmp.mygulfstream.com/Images/minus.gif> 712069 (P) Airframe Engine
Vibration Isolator (Left) - Clean = Inspect / Repair 120 MOS (C)=/span>

Due: End Of Month

Custom Frequency

MAN <https://cmp.mygulfstream.com/images/dotGreen.=if> 59 Mos

= Event Category

Special Inspection (M) PN Enter Par= Number

C/W Used Due Remains

Hrs: 7178.6

Lnd: 3292

Date: 15 Dec 2008

MO= 31 Dec 2018

59 Mos

Freq <javascript:op=nCustomFreq(3415308);> Next Due per Flight Utilization:&n=sp; 31 Dec 2018

SN

Mfg Ref Number: 71-01-00

Doc: R=v: =ssued: 01 Mar 1986

Section:

<=elect name="DocLinks" style="width: 180px; font-family: arial; font-si=e: 8pt;">DocumentsAMM 712069Task=20

Card <javascript:openCompImageLoader('3415308')> Watched Ops Package Last Upd=ted By: Martin Mroczek

Date: 1= Dec 2008 06:09 Est. =arts/Labor: \$0.00/0.00 Hrs.

<https://cmp.mygulfstream.com/C=mppliance/BudgetEstimate.aspx?ataNumber=712069> OEM Labor Hours:16.0

Mx. Notes: Special Notation: Show Related=Codes No Part Information S=ow C/W Adjustments

C/W Adjustments=/span>

=irframe Time used for Due Calculation =input name="opsSpec" id="opsSpec" type="checkbox" checked=""
value=3D"on">Ops Spec

Hours: Initial Frequency: N/A

Cycles: Recurring Frequency:<=font> 120 MOS Next due was not adjusted. <=tr>

Date: Frequency Tolerance:<=font> N/A

=input name="currentHoursComponent" type="hidden" value="8638.600"> <=nput name="currentCyclesComponent"
type="hidden" value="4005.000"> <=nput name="isPartRel" type="hidden">

Part Details

Manufac=urer: Install=20 Status: RB - RebuiltR - RepairedI - InspectedM - ModifiedN - NewO -

Overhauled Current Part Run Time: Hours Landings Months

TSN

TSO

TSR

Vendor:=nbsp; Mod Sta=us:
 HW Vers=on: Part Warranty:
 SW Vers=on: Labor=20 Warranty:
 Maint T=g: Airframe Time =t Install
 Hours:
 Cycles:
 Date:
 Part Time at=20 Install
 Hours Cycles [=onths or Date]
 TSN: = <javascript:doNothing();> </=> <javascript:doNothing();>
 TSR: <javascript:doNothing();> <=td>
 New Cos=:
 Overhau=ed:
 Repaire=:
 OEM Ven=or: Install=20 Notes: MAN <https://cmp.mygulfstream.com/images/dotGreen.=if> 59 Mos
 = Event Category
 Special Inspection (M) PN Enter Par= Number
 C/W Used Due Remains
 Hrs: 7178.6

 Lnd: 3292

 Date: 15 Dec 2008
 MO= 31 Dec 2018
 59 Mos
 Freq <javascript:op=nCustomFreq(3416340);> Next Due per Flight Utilization:&n=sp; 31 Dec 2018
 SN
 Mfg Ref Number: 71-01-00
 Doc: R=v: =ssued: 01 Mar 1986
 Section:
 <=elect name="DocLinks" style="width: 180px; font-family: arial; font-si=e: 8pt;">DocumentsAMM 712069Task=20
 Card <javascript:openComplImageLoader('3416340')> Watched Ops Package Last Upd=ted By: Martin Mroczek
 Date: 1= Dec 2008 06:09 Est. =arts/Labor: \$0.00/0.00 Hrs.
 <https://cmp.mygulfstream.com/C=mpliance/BudgetEstimate.aspx?ataNumber=712070> OEM Labor Hours:16.0
 Mx. Notes: Special Notation: Show Related=Codes No Part Information S=ow C/W Adjustments

 C/W Adjustments=/span>
 =irframe Time used for Due Calculation =input name="opsSpec" id="opsSpec" type="checkbox" checked=""
 value=3D"on">Ops Spec
 Hours: Initial Frequency: N/A
 Cycles: Recurring Frequency:<=font> 120 MOS Next due was not adjusted. <=tr>
 Date: Frequency Tolerance:<=font> N/A
 =input name="currentHoursComponent" type="hidden" value="8638.600"> <=nput name="currentCyclesComponent"
 type="hidden" value="4005.000"> <=nput name="isPartRel" type="hidden">

 Part Details
 Manufac=urer: Install=20 Status: RB - RebuiltR - RepairedI - InspectedM - ModifiedN - NewO -
 Overhauled Current Part Run Time: Hours Landings Months
 TSN
 TSO

TSR

Vendor:=nbsp;

Mod Sta=us:

HW Vers=on:

Part Warranty:

SW Vers=on:

Labor=20 Warranty:

Maint T=g:

Airframe Time =t Install

Hours:

Cycles:

Date:

Part Time at=20 Install

Hours Cycles [=onths or Date]

TSN: = <javascript:doNothing();> </=> <javascript:doNothing();>

TSR: <javascript:doNothing();> <=td>

New Cos=:

Overhau=ed:

Repaire=:

OEM Ven=or: Install=20 Notes: ATA 712070 Compliance History

Part ON # Serial ON # CW Hrs CW Cyc CW Date Actual Cost Work Order #

Part OFF # Serial OFF # Remark / Malfunction Actual Labor Facility

18903347)> 7,178.6 3,292 15 Dec 2008 0.00 [view] <javascript:openComplHistE=itor('3416340',

<javascript:openCompHistImageLoader('3416340',='18903347')>
0.00

2556375)> 3,601.0 1,644 11 Dec 1998 0.00 [view] <javascript:openComplHistE=itor('3416340',

<javascript:openCompHistImageLoader('3416340',='2556375')>
0.00 GAC-APP

5682341)> 1,020.0 413 05 Apr 1992 0.00 [view] <javascript:openComplHistE=itor('3416340',

<javascript:openCompHistImageLoader('3416340',='5682341')>
0.00

=/div>

712071 (P) Airframe Engine Isolator Mount Bolt Assembly (Left= Forward) - Scrap

P/N: 94756-07 S/N: 5302 8000 HRS</=pan>

Tolerance

+500 Hr Over Flight

MAN <https://cmp.mygulfstream.com/images/dotGree=.gif> 6540.0 Hrs

<=div>

712072 (P) Airframe Engine Isolator Mount Bolt Assembly (Righ=, Forward) - Scrap

P/N: 94756-07 S/N: 5319 8000 HRS</=pan>

Tolerance

+500 Hr Over Flight

MAN <https://cmp.mygulfstream.com/images/dotGree=.gif> 6540.0 Hrs

Event Category

Replacement (X) PN 94756-07* Enter Part Number

C/W Due Remains

Hrs: 7178.6

15178.6

6540.0

Lnd: 3292

Date: 15 Dec 2008

Freq <javascript:op=nCustomFreq(18270374);> Next Due per Flight Utilization:&n=sp; 31 Oct 2035

SN

Mfg Ref Number: 71-01-00

Doc: GIV AMM Rev: =4 Issued: 3= Apr 2013

Section: 05-02-00

<=elect name="DocLinks" style="width: 180px; font-family: arial; font-si=e: 8pt;">DocumentsAMM 712071Task=20

Card <javascript:openComplImageLoader('18270374')> Watched RII

Est. =arts/Labor: \$0.00/0.00 Hrs. OEM Labor Hours:0.0

Mx. Notes: compliance transfered from code 712018 Special Notation: Ops Spec

Hours: Initial Frequency: N/A

Cycles: Recurring Frequency:<=font> 8000 Hrs Next due was not adjusted. <=tr>

Date: Frequency Tolerance:<=font> +500 Hr Over Flight </=ont>

= =input name="currentCyclesComponent" type="hidden" value="4005.000"> =input name="isPartRel" type="hidden" value="1"> S - ServiceableTC - Time ContinuedI - InspectedM - ModifiedN - NewO - Overhauled Current Part Run Time:

Hours Landings Months

TSN

TSO

TSR

Vendor:=nbsp; Mod Sta=us:

HW Vers=on: Part Warranty:

SW Vers=on: Labor=20 Warranty:

Maint T=g: Airframe Time =t Install

Hours:

Cycles:

Date:

Part Time at=20 Install

Hours Cycles [=onths or Date]

TSN: <javascript:doNothing();> </=> <javascript:doNothing();>

TSR: <javascript:doNothing();> <=td>

New Cos=: \$635.64

Overhau=ed:

Repaire=:

OEM Ven=or: BARRY CONTROLS AEROSPACE Install=20 Notes:

Vendor =D: V000020996

Compliance Remarks

----- FOR REFERENCE ONLY -----

P/N 94756-07. Not to exceed 8500 hours. Reco=mended at scheduled engine overhaul.