
From: Mark L. Epstein <[REDACTED]>
Sent: Wednesday, January 14, 2015 11:43 PM
To: jeffrey E.
Subject: Re: Flaps

Not the motor. Each wing would have separate motors. Check switch mechanism in cockpit.

I had an auto pilot problem on IZMO. Replaced computer and had the control heads on pilot house and bridge redone . About \$3000.= Still no good. In bed one night it hit me. It was 2 \$20 relay=.

Sent via tin can and string.

On Jan 14, 2015, at 18:44, jeffrey E. <jeevacation@gmail.com <mailto:jeevacation@gmail.com>> wrote:

On Wed, Jan 14, 2015 at 7:23 PM, Mark L. Epstein [REDACTED]; wrote:

One wing or both?

Sent via tin can and string.

--

please no=e

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE. Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by jeevacation@gmail.com <mailto:jeevacation@gmail.com>, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

=