
From: Larry Visoski <[REDACTED]
Sent: Friday, February 10, 2017 6:27 PM
To: Je vacation; Rich Kahn
Subject: Boat delay
Attachments: IMG_0520.JPG; Untitled attachment 00310.txt

Fueled boat with 100 gallons,. By the time we got to the boat dock there was=strong odor of fuel, heading back to the shop with the boat to determine where the leak is, the g=od news, above the fuel tanks is dry where the fuel inlet located chances a=e right-hand fuel tank vent may have been disconnected