
From: Larry Visoski [REDACTED]
Sent: Wednesday, April 27, 2016 1:43 PM
To: Je vacation
Cc: Rich Kahn
Subject: GIV update

Jeffrey

Pete informs the FAMV "Fan Air Modulation Valves" where swapped last night, i's was a big job, the mechanics also located filter in Regulator valve that=is mounted on top of Fan Air valve, once they removed the filter, they noti=ed a metal filter screen on the R/H Air side of the Regulator valve with Ob=truction or FOD, "Foreign Object Debre" they put the screens in Ultra Sound=cleaner and reinstalled, Pete didn't feel the obstruction was large enough t= effect operation,

Ground runs / ops check this afternoon,

WiFi box in Tail compartment appears to have failed again, since SatPhone an= WiFi didn't work on yesterday flight, this will be warrantee exchange,

Will keep you advised

Thx
Larry

Sent from my iPhone=<?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
 <key>date-last-viewed</key>
 <integer>0</integer>
 <key>date-received</key>
 <integer>1461764567</integer>
 <key>flags</key>
 <integer>8590195713</integer>
 <key>gmail-label-ids</key>
 <array>
 <integer>5</integer>
 </array>
 <key>remote-id</key>
 <string>607317</string>
</dict>
</plist>