
From: Larry Visoski [REDACTED]
Sent: Tuesday, May 19, 2015 4:44 PM
To: Je vacation
Subject: Below floor
Attachments: IMG_5747.jpeg; Untitled attachment 00126.txt

Jeffrey

We are completing below floor under rear Lav., Since its easy inspection., =The pressurization silencer is located under trim tab control cables., I'll need 3 to 4 days to change this item, since cable rigging is involved., I'll request price for exchange outflow valve as well.,

- I'm also changing nose wheel tires today., Not sure if you noticed the vibration after nose wheels departs runway surface., Usually it's a balance or out-of-round condition.,

All will be finished tonight.,

Thx
Larry