
From: Lvjet [REDACTED] >
Sent: Saturday, June 27, 2015 8:57 PM
To: jeevacation@gmail.com
Subject: manifold

I spoke to Tech ops.,

45,000 feet, Test flight aircraft report., manifold pressure acceptable range is 20psi to 27psi,. single pack operation at 41,000 feet is 16 psi to 18psi we are reading 23psi on left and 26psi on right side manifold pressure, at FL450,. we are good here.

if Sock was freezing,. ice pellets like you heard on B727 would be rolling down air ducts according to Gulfstream,. I am have socks changed as preventive Mx.

thx