

To: Jeevacation[jeevacation@gmail.com]
From: Emad Hanna
Sent: Wed 7/28/2010 8:09:36 PM
Subject: Bentley Repairs

Jeffrey,

There are two issues on this:

- 1) The water pump had to be replaced and annual maintenance was done and that total including parts, labor and tax came to \$ 4,353.48
- 2) There is an issue with the assembly of the headlight where water is getting in and is shorting the tail light and left turn signal. The assembly and light will need to be replaced and that will cost \$ 1,720 plus tax.

#1 has been completed and I need to submit the payment. While the car is there we should get the headlight done as well. Are you ok with this?

Thank you

Emad Hanna

Project Controller

HBRK Associates

PO Box 400

New York, NY 10150

Ph

Fax