

To: jeevacation@gmail.com[jeevacation@gmail.com]
From: [REDACTED]
Sent: Mon 9/13/2010 7:08:11 AM
Subject: GIIB maintenance

Jeffrey,

I used the toasted for several minuets no faults noticed, all was operating correctly.

I have the Gulfstream being worked on at Meridian at Teterboro, the APU flamed out two times recently for no apparent reason, I heard a hissing sound from the exhaust before the APU flamed out, I suspect the fuel nozzle being plugged and not spraying a good pattern, which is necessary for jet fuel to burn under the high pressure. plus small interior cosmetic items and avionic items I would like repaired, Let me know if the schedule changes and when you think you will be ready to fly the Gulstream, I told them to have plane ready by Friday afternoon at the latest. I will keep you updated.

thank you,

Larry