

To: Je vacation[jeevacation@gmail.com]
From: [REDACTED]
Sent: Mon 4/26/2010 10:24:59 PM
Subject: N722JE

New radar MFD installed functional checked good, waiting on Honeywell's report on failed MFD's that have been installed on 750.

UPDATE April 26, 2010 18:00Over the last three days, all of the wiring connecting to the MFRD has been checked for correct termination points. Meg-ohm meter checks were performed. The wires were checked for proper voltages and grounds. No anomalies have been found.

Based upon a conversation between customer representatives and Honeywell Senior Field Service Engineer Greg Milton, MFRD S/N: 0448 was installed, configured and tested. The system is currently operating normally.

Honeywell Contact Information

Gregory R. Milton

Senior Field Service Engineer

Honeywell Aerospace

Phone

[REDACTED]

Sent from my BlackBerry® wireless handheld