

To: Jeffrey Epstein[jeevacation@gmail.com]
Cc: Gary Kerney [REDACTED]
From: Stephen Caplinger
Sent: Thur 1/28/2010 4:45:13 PM
Subject: Boat dock entry

According to Arran and the heavy equipment operators, the existing wall to the left of the drive can't be moved further into the drive due to minimum turning radius'. Widening the drive to the right would help but we still need to keep the big sweeping curve on the left.
You can see the double painted line on the drive which is 10' wide.
I'll send another photo from the statue looking back.

Sent from my iPhone

EFTA_R1_01500808
EFTA02430762