
From: [REDACTED] >
Sent: Monday, August 29, 2016 1:29 PM
To: Je vacation
Subject: Engine

Southwest airlines engine failure,
In my early opinion after further review of the photo enlarged,, Appears the spinner and fan is still intact and installed.
The engine did not fail but the surrounding cowling left the airplane could be in airframe issue not Engine Only an early guess

Sent from my iPhone=<?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN"
"http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
 <key>conversation-id</key>
 <integer>71190</integer>
 <key>date-last-viewed</key>
 <integer>0</integer>
 <key>date-received</key>
 <integer>1472477341</integer>
 <key>flags</key>
 <integer>8590195713</integer>
 <key>gmail-label-ids</key>
 <array>
 <integer>2</integer>
 </array>
 <key>remote-id</key>
 <string>639980</string>
</dict>
</plist>