

---

**From:** Richard Kahn <██████████>  
**Sent:** Tuesday, July 26, 2016 3:53 PM  
**To:** jeffrey E.  
**Subject:** Fwd: Honeywell system

ridiculous response..

Richard Kahn  
HBRK Associates Inc.  
575 Lexington =venue 4th Floor  
New York, NY 10022  
tel =██████████  
fax =██████████  
cell =██████████

Begin forwarded message:

From: =/b>Brice Gordon <██████████>

Subject: =/b>Re: Honeywell =ystem

Date: =/b>July 26, 2016 at 8:09:37 AM =DT

To: =/b>Richard Kahn <██████████>

Cc: Zorro Ranch <zorro.office@gmail.com>

Honeywell where on =ight Friday last week.  
there are some small programming issues that =ill be completed this week.  
there are some issues that we need to =ddress.

1.Thermostats in the =ollowing areas are reading wall temps

Kitchen

library

Great room

movie room

Fix is a foam plate is installed between =hermo and wall

I have already done this for 3 other areas =ome number of years ago.

2. We are getting =oisture in the duct work for living room , library and upstairs living =oom  
they =ll share the same make up air duct. this is causing some humidity =ssues  
We =re working on a solution

3.The system was =ever designed for consistent 95 degree plus days  
overall the house is running =K,

On Tue, Jul 26, 2016 at 4:20 AM, Richard Kahn =span dir="ltr" class=""><[REDACTED] wrote:

Is it working 100% =orrect?

Sent from my iPhone

--

Brice Gordon  
Stanley, =M

Ph: [REDACTED]

=