

---

**From:** Ann Rodriguez <annrodriquez@yahoo.com>  
**Sent:** Tuesday, June 28, 2016 7:53 PM  
**To:** Jeffrey  
**Subject:** GSJ: Master Bedroom  
**Attachments:** IMG\_0720.JPG; Untitled attachment 00225.txt; IMG\_0721.JPG; Untitled attachment 00228.txt; IMG\_0722.JPG; Untitled attachment 00231.txt; IMG\_0723.JPG; Untitled attachment 00234.txt; IMG\_0724.JPG; Untitled attachment 00237.txt; IMG\_0725.JPG; Untitled attachment 00240.txt; IMG\_0726.JPG; Untitled attachment 00243.txt; IMG\_0727.JPG; Untitled attachment 00246.txt; IMG\_0728.JPG; Untitled attachment 00249.txt; IMG\_0729.JPG; Untitled attachment 00252.txt; IMG\_0730.JPG; Untitled attachment 00255.txt; IMG\_0731.JPG; Untitled attachment 00258.txt; IMG\_0732.JPG; Untitled attachment 00261.txt; IMG\_0733.JPG; Untitled attachment 00264.txt

The blinds for the Windows are to small.

They're 30in and we need 36in for the new Windows.