
From: Larry Visoski [REDACTED]
Sent: Wednesday, April 27, 2016 1:43 PM
To: Je vacation
Cc: Rich Kahn
Subject: GIV update

Jeffrey

Pete informs the FAMV "Fan Air Modulation Valves" where swapped last night, i=s was a big job, the mechanics also located filter in Regulator valve that= is mounted on top of Fan Air valve, once they removed the filter, they noti=ed a metal filter screen on the R/H Air side of the Regulator valve with Ob=truction or FOD, "Foreign Object Debre" they put the screens in Ultra Sound=cleaner and reinstalled, Pete didn't feel the obstruction was large enough t= effect operation,

Ground runs / ops check this afternoon,

WiFi box in Tail compartment appears to have failed again, since SatPhone an= WiFi didn't work on yesterday flight, this will be warrantee exchange,

Will keep you advised

Thx
Larry

Sent from my iPhone=<?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>

```
<key>conversation-id</key>
<integer>81953</integer>
<key>date-last-viewed</key>
<integer>0</integer>
<key>date-received</key>
<integer>1461764567</integer>
<key>flags</key>
<integer>8590195713</integer>
<key>gmail-label-ids</key>
<array>
  <integer>2</integer>
</array>
<key>remote-id</key>
<string>607317</string>
```

```
</dict>
</plist>
```